

County: Sedgwick Fraction _____ Sec. 23 T 27 S R 2 E (W)

CORRECTION(S) TO WATER WELL COMPLETION RECORD (WWC-5)
(to rectify lacking or incorrect information)

Owner: Bernard Strecker

Location was listed as:

Section-Township-Range: 23

Fraction ($\frac{1}{4}$ $\frac{1}{4}$ $\frac{1}{4}$): NW SE SE

Location changed to:

23-27S-2W

NW SE SE

Other changes: Initial statements: _____

Changed to: _____

Comments: _____

Verification method: Well site address, city street map, and
mapping tool on KGS website.

initials: DRK date: 9/28/2012

Submitted by: Kansas Geological Survey, Data Resources Library, 1930 Constant Ave., Lawrence, KS 66047-3726
to: Kansas Dept of Health & Environment, Bureau of Water, 1000 SW Jackson, Suite 420, Topeka, KS 66612-1367.

KSA 82a-1212