

PHONE
(316) 722-1411



HARP WELL & PUMP SERVICE, INC.

Water Well Drilling — Piling Hole Drilling — Test Drilling
Gravel Packed Wells for
Home — Industrial — Municipal — Irrigation
PUMP SALES & SERVICE

215 SO. TYLER ROAD WICHITA, KANSAS 67209

March 6, 2000

Mr. Don Taylor
Environmental Geology Unit
Industrial Programs Section
Bureau of Water

Re: changes in fraction, section number, township number, distance and direction and address.

The log is for Eric Lamp dated 4-2-99. The correct fraction should have been SW NW NE. Correct section number is 7. Correct township number is 28. Correct distance is 31st & Maize Road, 1/2 West. Correct address is 11101 W. 31st South.

I am sending a copy of the log in error as well as a corrected copy.

Because of Y2K problems, Todd's name came out in large bold print, he has signed his name under the printed version.

I am sorry for any inconvenience this may cause you.

Thank You.

Sincerely,

A handwritten signature in cursive script that reads "Jane Frederick".

Jane Frederick
Water Log Department

RECEIVED

MAR 07 2000

BUREAU OF WATER

077
3-900