



MIDWEST SURVEYS
LOGGING - PERFORATING - CONSULTING SERVICE
P.O. Box 68, Osawatomie, KS 66064
913 / 755 - 2428

AMMA RAY / NEUTRON / CCL

R.I. Enterprises Of Kansas, LLC.

Pearson No.-33

Baldwin

Douglas State Kansas

2440' FSI & 520' FFI

NW-NE-NE-SE

wp. 135 Rge. 206

[illegible]

GL Measured From

	1-10-2013	
--	-----------	--

One

960.0	
-------	--

304.0

000	
000	
000	

	E
--	---

	Water	
--	-------	--

 $\mathbb{N}$

	NA	
--	----	--

	NA	
--	----	--

2	0	8
---	---	---

	Ganz Mundlich
--	---------------

Lance Town

3-HOLE RECORD	CASINO
---------------	--------

FROM	TO	SIZE	WGT.
------	----	------	------

0.0	703.0	7.00	77.0#
0.0			

100.0	900.0	2.0/0.7	0.4/0.0
-------	-------	---------	---------

[illegible][illegible]

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Town Oilfield Services, Inc.

Database File: pearson33.db
Dataset Pathname: pass1
Presentation Format: gr-n-ccl

