



Pioneer Energy Services

Dual Compensated Porosity Log

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments


Thank you for using Pioneer Energy Services
www.pioneerres.com
785 625 3858


PLAINVILLE KS, SOUTH TO AA RD,
7 1/2 WEST, 1/4 NORTH, EAST INTO

Database File	amwar_tomasheck #1-10\americanwarrior_tomasheck_1_10hd.db
Dataset Pathname	DIL/awstk
Presentation Format	cdl
Dataset Creation	Mon May 25 09:30:51 2015
Charted by	Depth in Feet scaled 1:600

0	Gamma Ray	150
6	Caliper (in)	16

30	Compensated Density	-10
2	Bulk Density	3
15000	Line Tension	0
-0.25	Correction	0.25
LSPD		





Database File amwar_tomasheck #1-10\americanwarrior_tomasheck_1_10hd.db
 Dataset Pathname DIL/awstk
 Presentation Format cndlspec
 Dataset Creation Mon May 25 09:30:51 2015
 Charted by Depth in Feet scaled 1:240

