
NO ROAD

Notes;

- 1. Set iron rod at location site.
- 2. All flagging Red & Yellow.
- 3. No overhead power available at Sec. 18.
- 4. Kansas One Call System Inc. should be notified before excavation (1-800-344-7233).
- 5. CAUTION: Various pipelines in Sec. 18.
- 6. Section 18 is irregular E-W.
- 7. Contact landowner for best access.



| ı | FAS 963 [] | , m | 1 II II II | | 1 1 1 | TAS |
|--|-------------------------------|----------|-------------------|-------------|----------------|-------------|
| | Middle Craig | 1 6 FAS | 1365 | 1 // 6 | 7 FAS 1365 | 1 6 EAS EAS |
| Z Krawa | } | | | Creek 31 | 3 | 38 |
| 5 | Kidille | 18 | | FA P | FAS 1737 | FAS |
| 5 3 | | 又ノ | | 5 183 } | | Wilmore |
| Net of the state o | | FAS 1737 | 1 | (FAS) | 3 | FAS |
| 13T PAS 771 | 7 | 38 31 | | 36131 | / 5 } | . 36 31 |
| 3 | is distribution of the second | 1 8 | | Fg / 16 . / | (160) FAP 18 | |
| 8: 3 m | FAS | FAS \155 | | | (60) | |
| | Kiowa | | | cc | LDWATER | Nes S |
| | XI I | | 1511-1271 | Man I | K I C X | K & (|

^{*} Controlling data is based upon the best maps and photographs available to us and upon a regular section of land containing 640 cares.

* Elevations derived from National Geodetic Vertical Datum.

July 13, 2010

^{*}Approximate section lines were determined using the normal standard of care of oilfield surveyors practicing in the state of Kansas. The section corners, which establish the precise section lines, were not necessarily located, and the exact location of the drillsite location in the section is not guaranteed. Therefore, the operator securing this service and occepting this plat and all other parties relying thereon agree to hold Central Kansas Dilfield Services. Inc., its officers and employees harmless from all losses, costs and expenses and said entities released from any liability from incledantal or consequential damages