
RICKETTS	TESTING			(620) 326-5830	Р	Page 1			
Company Address CSZ Attn.	Shelby Resou 445 Union Bly Lakewood, Co Charlie Sturda	d. Ste. 208 D 80228		Lease Name Lease # Legal Desc Section Township County	McCune 1-8 NE-SW-NW-SW 8 25S Stafford	Range State	t 2143 12W KS		
Comments	Field: Bunyan Northeast Legal Description Feet; 1600' FSL & 350' FWL								
GENERAL IN	NFORMATIO	N							
Test # 4 Tester Test Type	Tim Venters Conventional Bottom Hole		3/10/2011 e	Chokes Top Recorder # Mid Recorder # Bott Recorder #	# W1022				
# of Packers Mud Type Mud Weight Filtrate	Successful Te 2.0 Gel Chem 9.0 6.4	Packer Size Viscosity Chlorides	51.0 5500	Time on Site Tool Picked Up	0 Jars & Safety jo 6:35 PM 8:35 PM	Approved By			
Drill Collar Len Wght Pipe Len				Tool Layed Dwr Elevation		Kelley Bushings1	912.00		
Formation Interval Top Anchor Len Bel Total Depth Blow Type	Lansing "K" Start Date/Time3/9/2011 7:34 PM 3780.0 Bottom 3808.0 End Date/Time 3/10/2011 4:31 AM								
RECOVERY									

Feet	Description	Gas	OII	water	Mud
	Gas in Pipe Very slight oil cut mud Gassy, oil and water cut mud	100%450ft 0% 0ft 10% 6ft	0% Oft 1% 1.2ft 22% 13.2ft	0% Oft 0% Oft 15% 9ft	0% 0ft 99% 123.8ft 53% 31.8ft

32000 **DST Fluids**



GAS FLOWS

Min Into IFP Min Into FFP Gas Flows Pressure Choke