MORNING COMPLETION REPORT

| LEASE NAME & # WESTFALL 14Q-1 | | AFE# | DATE | DAYS | CIBP | PBTD: |
|----------------------------------|--|-------------------|-----------------|--------|----------------------|---|
| | | | | | DEPTH | TYPE FLUID |
| | | | 5/11/2011 | 1 | TYPE | |
| PRESENT OPERATI | ON: | | | | | WT |
| EEPEST CASING | LINERS OD TOP & S | HOE DERTH | REPAIR DOWN TII | AE UDO | I COUTT LOT OF | VIS |
| D SHOE DEPTH | LINERS OD TOP & S | HOE DEPTH | REPAIR DOWN III | WE HKS | CONTRACTOR RIG NO | |
| | | | TEST PE | RFS | RIG NO | |
| PACKER OR ANCHOR_ | FISHING TOOLS | OD ID | | | | TEST PERFS |
| | | | | | то | |
| | | | | | | то |
| | | | | | | то |
| | | | | | | |
| HRS | BRIEF DESCRIP | TION OF OPERA | ATION | | | |
| | | | | | | |
| | MIRU Thornton, drilled 11" hole 22' deep, RIH W/1 joint 8-5/8" surface casing. Mixed 4 sx type 1 | | | | | |
| | cement, dumped down the backside. SDFN. | | | | | |
| | Cernent, dumped | down the backsion | UE. SUFN. | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | , | | | | |
| | | | | | | |
| | | | | | | |
| AILY COST ANALY | 'SIS | | | | | |
| | | | | | | |
| 210 | | | | | DETAILS OF RENTALS | , SERVICES, & MISC |
| RIG | | | | SUP | ERIOR WIRELINE | |
| | | | | SUP | ERIOR FRAC CREW | |
| SUPERVISION | | | | | KS TANKS | |
| | | | | | | |
| | | | | | C VALVE | |
| ENTALS | | | | HOR | TON TOOL CO. | |
| | | | | | | |
| | | | | | | |
| RVICES | | | | | | *************************************** |
| ERVICES | | | | | | |
| ERVICES | | | | - | | |
| ERVICES | | | | | | |
| | | | | | | 0 |