MORNING COMPLETION REPORT

Report Called in by: JM

Report taken by: KRD

LEASE NAME & #	AFE#	DATE	DAYS	CIBP	PBTD
SHULTZ 4D-2		3/30/2011	1	DEPTH / TYPE	TYPE FLUID
PRESENT OPERATION:					WT
TD, OHL, CSG, CMT.					VIS

DEEPEST CASING OD SHOE DEPTH	LINERS OD TOP & SHOE DEPTH	REPAIR DOWN TIME HRS	CONTRACTOR MOKAT
	8 5/8" 24# J-55 --- Set 21.5'		RIG NO BILLY

PACKER OR ANCHOR	FISHING TOOLS OD ID	TEST PERFS	SQUEEZED OR PLUG BACK PERFS
		TO	TO
		TO	TO
		TO	TO
		TO	TO

HRS	BRIEF DESCRIPTION OF OPERATION
	MIRU Thornton, drilled 11" hole 21.5' deep, RIH W/1 joint 8-5/8" surface casing. Mixed 4 sx type 1 cement, dumped down the backside. SDFN.

DAILY COST ANALYSIS

		DETAILS OF RENTALS, SERVICES, & MISC
RIG		MOKAT DRILLING @ 6.50/ft
		MOKAT DAYWORK
SUPERVISION		DIRTWORKS (LOC,RD, PIT)
		SURFACE CASING
RENTALS		LAND/ LEGAL
		WL
SERVICES		CONS.
		FLOAT
MISC		CSG

DAILY TOTALS 0 *PREVIOUS TCTD* 0 *TCTD* 0