MORNING COMPLETION REPORT

Report Called in by: JACOB Report taken by:

LEASE NAME & #	AFE#	DATE	DAYS	CIBP	PBTD:
OSBURN 14-11		10/10/2011	1	DEPTH / TYPE	TYPE FLUID
PRESENT OPERATION: SET SURFACE PIPE					WT / VIS

DEEPEST CASING OD SHOE DEPTH	LINERS OD TOP & SHOE DEP	REPAIR DOWN TIME HRS	CONTRACTOR MOKAT
84' OF 8-5/8			RIG NO
		TEST PERFS	
PACKER OR ANCHOR	FISHING T OD ID		TEST PERFS
			TO
			TO
			TO

HRS	BRIEF DESCRIPTION OF OPERATION
	MIRU THORNTON DRILLING, DRILLED 11" HOLE, 85' DEEP, RIH W/4 JT 8 5/8" SURFACE CASING,
	RIGGED UP CONSOLIDATED TO 8-5/8 SURFACE CASING, BREAK CIRCULATION WITH FREASH WATER
	MIXED 65 SKS CLASS A CEMENT WITH 3% CALC 2 % GEL & 1/4# FLO SEAL PER SK. DIDN'T GET CEMENT
	CIRCULATED TO TOP OF HOLE. SAND AND 11' FROM SURFACE TAKING CEMENT RETURNS. JOB COMPLETE
	RIG DOWN.

DAILY COST ANALYSIS

RIG	2100
SUPERVISION	
RENTALS	
SERVICES	4946.81
MISC	1250

DETAILS OF RENTALS, SERVICES, & MISC

DRILLING	2100
CEMENT	2446.81
DIRTWORKS (LOC,RD, PIT)	2500
SURFACE CASING	1250
LAND/ LEGAL	
	8296.81

DAILY TOTALS 8296.81 ***PREVIOUS TCTD*** 0 ***TCTD*** 8296.81