



### Cement Report

Customer <i>L B Exploration</i>		Lease No.		Date <i>9-15-11</i>		
Lease <i>Houkins Ranch</i>		Well # <i>1</i>		Service Receipt		
Casing <i>5 5/8 14'</i>	Depth	County <i>Barber</i>	State <i>Ks</i>			
Job Type <i>2-42 Longshing</i>	Formation	Legal Description <i>28-32-13</i>				
Pipe Data			Perforating Data		Cement Data	
Casing size <i>5 5/8 14</i>	Tubing Size	Shots/Ft		Lead		
Depth <i>4991</i>	Depth	From	To	Tail in <i>1755Ks</i> <i>AA-2</i>		
Volume <i>121</i>	Volume	From	To			
Max Press <i>2000</i>	Max Press	From	To			
Well Connection	Annulus Vol.	From	To			
Plug Depth <i>4949</i>	Packer Depth	From	To			
Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log	
<i>6:30</i>					<i>on location</i>	
<i>6:45</i>					<i>rig up</i>	
<i>10:10</i>					<i>Drop Ball</i>	
<i>10:20</i>					<i>start circulating</i>	
<i>11:05</i>					<i>shut down circulation Hook to cement</i>	
<i>11:25</i>	<i>0</i>		<i>12</i>	<i>1.7</i>	<i>plug Rat &amp; mouse Hole</i>	
<i>11:40</i>	<i>0</i>		<i>1</i>	<i>0.75</i>	<i>start cement for pipe 15.3'</i>	
<i>11:40</i>	<i>0</i>		<i>1</i>	<i>0</i>	<i>shut down to fix Recirculating Pipe</i>	
<i>12:35</i>	<i>200</i>		<i>1</i>	<i>2.75</i>	<i>start cmt. 15.3'</i>	
<i>12:55</i>	<i>0</i>		<i>44</i>	<i>0</i>	<i>shut down to wash up lines &amp; pump</i>	
<i>1:05</i>	<i>0</i>		<i>0</i>	<i>0</i>	<i>Drop plug</i>	
<i>1:08</i>	<i>0</i>		<i>1</i>	<i>4.0</i>	<i>start disp</i>	
<i>1:52</i>	<i>1500</i>		<i>122</i>	<i>0</i>	<i>plug down</i>	
<i>1:53</i>					<i>Release Pressure Plug Holding</i>	
<i>1:55</i>					<i>Rig down</i>	
Service Units		<i>27462</i>	<i>14354</i>	<i>19573</i>	<i>17702</i>	
Driver Names						

*[Signature]*  
Customer Representative

\_\_\_\_\_  
Station Manager

*[Signature]*  
Cementer Taylor Printing, Inc.