



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED
MAY 03 2012

Test Ticket

NO. 47723

BY:

Well Name & No. Reichert #1 Test No. 5 Date 5/1/12
 Company Double D's LLC Elevation 1988 KB 1981 GL
 Address 133 E 12th Hays KS 67601
 Co. Rep / Geo. Al Downing Rig Discovery #3
 Location: Sec. 23 Twp. 15 Rge. 19 Co. Ellis State KS

Interval Tested 3595 - 3620 Zone Tested Congl sd
 Anchor Length 25 Drill Pipe Run 3550 Mud Wt. _____
 Top Packer Depth 3590 Drill Collars Run 30 Vis _____
 Bottom Packer Depth 3595 Wt. Pipe Run — WL _____
 Total Depth 3620 Chlorides _____ ppm System LCM _____
 Blow Description IF - 1/2 in blow
IST - No blow
FF - No blow flash tool work surface blow

Rec	Feet of	%gas	%oil	%water	%mud
<u>15</u>	<u>SOCM</u>		<u>5</u>	<u>95</u>	
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 15 BHT _____ Gravity _____ API RW _____ @ _____ °F Chlorides _____ ppm

(A) Initial Hydrostatic 1820 Test 1150 T-On Location 10:40
 (B) First Initial Flow 20 Jars _____ T-Started 10:55
 (C) First Final Flow 21 Safety Joint _____ T-Open 13:30
 (D) Initial Shut-In 571 Circ Sub _____ T-Pulled 14:50
 (E) Second Initial Flow 22 Hourly Standby _____ T-Out 16:10
 (F) Second Final Flow _____ Mileage 16x2 49.60 Comments _____
 (G) Final Shut-In _____ Sampler _____
 (H) Final Hydrostatic 1708 Straddle _____ Ruined Shale Packer _____
 Shale Packer _____ Ruined Packer _____
 Extra Packer _____ Extra Copies _____
 Initial Open 30 Extra Recorder _____ Sub Total 0
 Initial Shut-In 30 Day Standby _____ Total 1199.60
 Final Flow 20 Accessibility _____ MP/DST Disc't _____
 Final Shut-In _____
 Sub Total 1199.60

Approved By _____ Our Representative Ben Davis

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.