

Kepley Well Service, LLC

19245 Ford Road
Chanute, KS 66720

| Date | Invoice # |
|-----------|-----------|
| 2/15/2012 | 46598 |

Cement Treatment Report

Lorotta Oil, LLC
543A 22000 Road
Cherryvale, KS 67335

(x) Landed Plug on Bottom at 600 PSI
 () Shut in Pressure 700
 (x) Good Cement Returns
 () Topped off well with _____ sacks
 (x) Set Float Shoe

TYPE OF TREATMENT: Production Casing
 HOLE SIZE: 6 1/2"
 TOTAL DEPTH: 360

| Well Name | Terms | Due Date | | |
|-----------------------|-------------|-------------------------------|----------|--|
| | Net 15 days | 2/15/2012 | | |
| Service or Product | Qty | Per Foot Pricing/Unit Pricing | Amount | |
| Run and cement 2 7/8" | 350 | 3.00 | 1,050.00 | |
| Sales Tax | | 7.30% | 0.00 | |

Mechling #C-2
Crawford County
Section:
Township:
Range:

Hooked onto 2 7/8" casing. Established circulation with 2.5 barrels of water, 2 GEL, METSO, COTTONSEED ahead, blended 61 sacks of OWC cement, dropped rubber plug, and pumped 2 barrels of water

| | |
|------------------|------------|
| Total | \$1,050.00 |
| Payments/Credits | \$0.00 |
| Balance Due | \$1,050.00 |