



4710

**TRILOBITE  
TESTING INC.**

P.O. Box 1733 • Hays, Kansas 67601

**Test Ticket**

NO. 47232

Well Name & No. Veley-Riedel #2 Test No. 1 Date 5-12-12  
 Company Michael D. Weiler Oil Company Elevation 2237 KB 2228 GL  
 Address 866 2307K Ave, Hays, KS 67601  
 Co. Rep / Geo. Michael Weiler Rig Integrity #7  
 Location: Sec. 7 Twp. 14S Rge. 19W Co. Ellis State KS

Interval Tested 3489-3570 Zone Tested 104070 - C" Mud Wt. 9.3  
 Anchor Length 81' Drill Pipe Run 3499 Vis 53  
 Top Packer Depth 3484 Drill Collars Run 0 WL 8.4  
 Bottom Packer Depth 3489 Wt. Pipe Run 0 LCM 0#  
 Total Depth 3570 Chlorides 7000 ppm System

Blow Description FF - Very weak building blow. Built to 6 inches.  
FST - No Return.  
FF - Very weak building blow. Built to 4 inches.  
FST - No Return.  
 Rec 110 Feet of USOCM %gas 3 %oil 3 %water 97 %mud  
 Rec \_\_\_\_\_ Feet of \_\_\_\_\_ %gas \_\_\_\_\_ %oil \_\_\_\_\_ %water \_\_\_\_\_ %mud  
 Rec \_\_\_\_\_ Feet of \_\_\_\_\_ %gas \_\_\_\_\_ %oil \_\_\_\_\_ %water \_\_\_\_\_ %mud  
 Rec \_\_\_\_\_ Feet of \_\_\_\_\_ %gas \_\_\_\_\_ %oil \_\_\_\_\_ %water \_\_\_\_\_ %mud  
 Rec \_\_\_\_\_ Feet of \_\_\_\_\_ %gas \_\_\_\_\_ %oil \_\_\_\_\_ %water \_\_\_\_\_ %mud

Rec Total 110 BHT 110 @ \_\_\_\_\_ F Chlorides \_\_\_\_\_ ppm  
 (A) Initial Hydrostatic 1804 Gravity  test 1150 T-On Location 1900  
 (B) First Initial Flow 31  Jars 0 T-Started 2115  
 (C) First Final Flow 58  Safety Joint 0 T-Open 2326  
 (D) Initial Shut-In 615  Circ Sub 0 T-Pulled 0330  
 (E) Second Initial Flow 57  Hourly Standby XZ 200 T-Out 0600  
 (F) Second Final Flow 72  Mileage 12XZ Comments BAT-2116  
 (G) Final Shut-In 593  Sampler \_\_\_\_\_  
 (H) Final Hydrostatic 1679  Straddle \_\_\_\_\_

Shale Packer \_\_\_\_\_  Ruined Shale Packer \_\_\_\_\_  
 Extra Packer \_\_\_\_\_  Ruined Packer \_\_\_\_\_  
 Extra Recorder \_\_\_\_\_  Extra Copies \_\_\_\_\_  
 Day Standby \_\_\_\_\_ Sub Total 0  
 Accessibility \_\_\_\_\_ Total 1368.60  
 Sub Total 1368.60 MPDST Disc'l \_\_\_\_\_

Approved By \_\_\_\_\_ Our Representative [Signature]  
 Trilobite Testing Inc. shall not be liable for damaged or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.