

GEOLOGICAL REPORT

Flowers Production Co.,Inc.

Franklin #1A

SE SE SW Section 26 T24S R2E

Harvey Co. Ks

COMMENCED: 8/9/2012

COMPLETED: 8/13/2012

CONTRACTOR: Gulick Drilling Co.

SIZE OF HOLE: 7 7/8"

SURFACE IPIPE: 220'

CEMENTED WITH: NA

LONG STRNG: NONE

CEMENTED WITH: N/A

RTD:2990

STATUS: Dry

A.P.I.#: 15-079-20694

OPERATOR LIC : 6407


FIELD: Dubois

ELEVATION: 1406 KB

LOGS: CNT,CST,LDT,MLT,PIT

MUD SYSTEM: Chemical

OTHER:



William L Jackson
Geologist