

Lasso Energy LLC - Carver#1 – Corrected C-1 Information

The Carver #1 (API 15-035-19261-00-01) is a re-entry of the Tanner #1 from 1959. The Tanner #1 “feet from section line” information in KGS was incorrect. Lasso Energy LLC’s original Intent to Drill C-1 was prepared with reference to KGS data. From the south line of the section, the footage is actually 660 feet, whereas KGS had incorrect data of 1320 feet from the south line of the section. Lasso Energy LLC’s corrected C-1 for the Carver #1 reflects the accurate spot location and footages.