

**CLOSURE OF SURFACE PIT**

| | |
|--|---|
| Operator Name: | License Number: |
| Operator Address: | |
| Contact Person: | Phone Number: () - - - |
| Permit Number (API No. if applicable): | Lease Name & Well No.: |
| Type of Pit: <input type="checkbox"/> Emergency Pit <input type="checkbox"/> Burn Pit <input type="checkbox"/> Settling Pit <input type="checkbox"/> Drilling Pit <input type="checkbox"/> Workover Pit <input type="checkbox"/> Haul-Off Pit | Pit Location (QQQQ): _____ - _____ - _____ - _____ Sec. _____ Twp. _____ R. _____ <input type="checkbox"/> East <input type="checkbox"/> West _____ Feet from <input type="checkbox"/> North / <input type="checkbox"/> South Line of Section _____ Feet from <input type="checkbox"/> East / <input type="checkbox"/> West Line of Section _____ County |
| Date of closure: _____ | |
| Was an artificial liner used? <input type="checkbox"/> Yes <input type="checkbox"/> No | |
| If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? | |
| Abandonment procedure of pit: | |

Submitted Electronically

Summary of Changes

Lease Name and Number: Gleue Trust, E & I (852) K8-i

API/Permit #: 15-031-23366-00-00

Doc ID: 1110638

Correction Number: 1

| Field Name | Previous Value | New Value |
|--|---|---|
| Approved Date | 12/27/2012 | 01/31/2013 |
| Is Footage Measured from the East or the West Section Line | West | East |
| LocationInfoLink | https://solar.kgs.ku.edu/kcc/detail/locationInformation.cfm?section=36&t2475 | https://solar.kgs.ku.edu/kcc/detail/locationInformation.cfm?section=36&t2805 |
| Number of Feet East or West From Section Line | 2475 | 2805 |
| Number of Feet North or South From Section Line | 825 | 872 |
| Save Link | ../kcc/detail/operatorEditDetail.cfm?docID=1105948 | ../kcc/detail/operatorEditDetail.cfm?docID=1110638 |