EDWARD E BIR 302 SOUTH 16TH BURLINGTON, 620-364-1311 - OH CHARGE TO ADDRESS LEASE & WELL, KIND OF JOB DIR. TO LOC.	WELL CEMENTING KS 66839 FFICE, 620-364-6719 - CELL COUNTY C. DATE: 10/23/12 CITY O ST ZIP
QUANTITY	MATERIAL USED SERV. CHG
120 SX	Portland Cement
7	
	BULK CHARGE
	BULK TRK. MILES
	PUMP TRK. MILES
	PLUGS
	TOTAL
T.D. 102	5
SIZE HOLE 5	7/8" TBG SET AT VOLUME_
	SIZE PIPE 27/8"
PLUG DEPTH	PKER DEPTHPLUG USED
TIME FINISHED:	
REMARKS: OF	nnect to gipe. Pump coment into well. Good circ. to
NAME	Eduard Birk
CEMENTER OF	R TREATER OWNER'S REP.
OZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZ	O ITALIAN D IUA .

802 N. Industrial Rd. P.O. Box 664 Iola, Kansas 66749 Phone: (620) 365-5588

Payless Concrete Products, Inc.

300.00

BI/J. ROLF B & B COOPERATIVE VENTURES. 58 W TO WAYSIDE N 2 MI TO 6TH E ON N SD @ TANKS

BB881: B & B COURERATIVE VENTURES 900 S. FOUNTH ST.

BURLINGTON KS

		00003			CEHSELIUSIAN MULT WEB		
TIME	FORMULA	LOAD SIZE	YARDS ORDERED		DRIVER/TRUCK		PLANT/TRANSACTION #
12:46:52p	NELL	12.00 yd	12.00 yd !	% CAL 0.00	35	0.00 % HIR	corco
DATE	10	LOAD#	YARDS DEL.	BATCH#	WATER TRIM	SLUMP	TICKET NUMBER
10-23-12	o Date	11	132.00 yd 1 12.00 yd	22431	G/yd 0.0	4700 in	32905
		THE PURIOUS REPORTS OF THE PROPERTY OF THE PARTY OF THE P	The state of the s	*			

WARNING

IRRITATING TO THE SKIN AND EYES
Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY
CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of
Contact With Skin or Eyes, Flush Thoroughly With Water, if Irritation Persists, Get Medical
Attention. KEEP CHILDREN AWAY.

CONCRETE IS A PERISHABLE COMMODITY and BECOMES the PROPERTY Of the PURCHASER UPON LEAVING the PLANT. ANY CHANGES OR CANCELLATION of ORIGINAL INSTRUCTIONS MUST be TELEPHONED to the OFFICE BEFORE LOADING STARTS.

The undersigned promises to pay all costs, including reasonable attorneys' fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 24% per annum. Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$25 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks. Excess Delay Time Charged @ \$50/HR. CODE

QUANTITY

PROPERTY QAMAGE RELEASE

(TO BE SIGNED IF DELIVERY TO SE WADE INSIDE CURB UNE)

Dear Customer-The driver of this truck in presenting this RELEASE to you for your signature is of the pointon that the size and weight of his truck may possibly cause damage to the premises endior adjacent property if it places the material in this load where you desire it. It is our wish to help you in every well that we can, but in order to do this the driver is requesting that you significant property buildings, sidewalks, officeways, curbs, etc., by this Gebever of this material, and that you also garee to help him renove gligant property, buildings, sidewalks, officeways, curbs, etc., by this Gebever of this material, and that you also agree to help him renove imade from the wheels of his weblied so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisin out of delivery of this order.

Excessive Water is Detrimental to Concrete Performance H₂0 Added By Request/Authorized By

WEIGHMASTER

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

25.00

12.00

UNITPRICE EXTENDED PRICE 12.00 51,00 612.00

12.00 WELL WELL (10 SACKS PER UNIT) MIXING & HAULING 12.00 MIXXHOUL Trucking Charge

DESCRIPTION

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	DELAY EXPLANATION/CYLINDER TEST TAKEN	TIME ALLOWED	SubTotal 4 912.00
	5:00		1. JOB NOT READY 6. TRUCK BROKE DOWN 2. SLOW POUR OR PUMP 7. ACCIDENT 3. TRUCK AHEAD ON JOB 8. CITATION		Tax x 1 6.300 57.46 Total 1 969.46
LEFT PLANT	ARRIVED JOB	START UNLOADING	CONTRACTOR BROKE DOWN 9. OTHER ADDED WATER	TIME DUE	Order's 969,46
(1,02.	1:34				ADDITIONAL CHARGE 1
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME		DELAY TIME	ADDITIONAL CHARGE 2
				,	GRAND TOTAL