BIRK PETROLE 874 12 TH RD SW BURLINGTON,	WELL CEMENTING	SERVICE TICKET
	FFICE, 620-364-6646 - CELL	DATE: 11/08/12
CHARGE TO	birk Petroleum COUNTY Cf.	CITY
ADDRESS	CITY ST	ZIP
LEASE & WELL		ny 700 IS
KIND OF JOB DIR. TO LOC.	ement long string sectwpre	OLD NEW
QUANTITY	MATERIAL USED	SERV. CHG
120 SX	Portland Cement	
Ĉ		
	BULK CHARGE	
	BULK TRK. MILES	
	PUMP TRK. MILES	
	PLUGS	
	TOTAL	
T.D. 1006	CSG. SET AT 990'	VOLUME
SIZE HOLE 5	78 'I TBG SET AT	VOLUME
MAX. PRESS	27611	
PLUG DEPTH	PKER DEPTH F	LUG USED
TIME FINISHED:		
REMARKS	aned to pine. Pumo ament 1	nto well. Good
CIC T	Surface! Top complete.	
Landard Maria Comment		
NAME	:	
		21
ODAEA WED O	R TREATER OWNER'S REP.	
CEMENTER O	VIREATER OWNER SKEP.	

02 N. Industrial Rd. P.O. Box 664 Iola, Kansas 66749 Phone: (620) 365-5588



vater contents for strength or mix indicated, we do no strength test when water is added at customer's request NOTICE TO OWNER "allure of this contractor to pay those persons supply complete this contract can result in the filing of a mech which is the subject of this contract.

SHIP TO

EXTENDED PRICE

BB001

B & B COOPERATIVE VENTURES 900 S. FOURTA ST.

BURLINGTON K8

echao

BI/HAZEN A B & B COOP. VENTURES/BIRK OIL 58 W TO WAYSIDE RD N 1 1/2 MT

WELL# HAZEN A #15

F POV KE EERST

TIME	FORMULA	LOAD SIZE	YARDS ORDERED		DRIVER/TRUCK		PLANT/TRANSACTION #
				% CAL	Principal Control of C	% AIR	
02:06:58p	WELL	12.00 yd	12.00 yd	0.00	31.	0.00	COFCO
DATE		LOAD #	YARDS DEL.	BATCH#	WATER TRIM	SLUMP	TICKET NUMBER
	To Date	1	12.00 yd				· A STANKEN
11-08-12	Today	1	12.00 yd	22636	6/yd Ø. Ø	4.00 in	x 33057

WARNING

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY (AUSE BURNS, Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water, If Irritation Persists, Get Medical Attention. KEEP CHILDREN AWAY.

CONCRETE IS A PERISHABLE COMMODITY and BECOMES the PROPERTY of the PURCHASER UPON LEAVING the PLANT. ANY CHANGES OR CANCELLATION of ORIGINAL INSTRUCTIONS MUST be TELEPHONED to the OFFICE BEFORE LOADING STARTS.

The undersigned promises to pay all costs, including reasonable attorneys fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 24% per annum. Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$25 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks

PROPERTY DAMAGE RELEASE

PROPERTY DAMAGE RELEASE

(TO BE SIGNED IF DEUTERY TO BE MADE INSIDE CURB LINE)

Dear Oustomer-The other of this truck in presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may, possibly cause damage to the premises and/or adjacent property if it places the material in this load where you desire ji, it is our wish to help you lin every way that we can, but in order to vide this driven for the premises and/or adjacent property, buildings, sidewalks, driveways, curbs, etc., by the delivery of this material, and that you also agree to help him remove must from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisin out of delivery of this order.

Excessive Water is Detrimental to Concrete Performance H₂0 Added By Request/Authorized By

GAL X

WEIGHMASTER

X Excess Delay Time Charged @ \$50/HR. QUANTITY CODE UNIT PRICE DESCRIPTION

12.00 WELL WELL (10 SACKS PER UNIT) 12.00 51,00 612.00 12.00 MIXAHAUL MIXING & HAULING 12.00 25.00 300.00 TRUCKING TRUCKING CHARGE 2.50 1 50.00

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	DELAY EXPLANATION/CYLINDER TEST TAKEN		TIME ALLOWED		
4.45	4.45		JOB NOT READY SLOW POUR OR PUMP TRUCK AHEAD ON JOB	TRUCK BROKE DOWN ACCIDENT CITATION		SubTotal \$ 1037.00 Tax % 6.300 (454 65.33	
LEFT PLANT	ARRIVED JOB	START UNLOADING	CONTRACTOR BROKE DOWN ADDED WATER	9. OTHER	TIME DUE	Total \$ 1400 ments	
*227	3,60					ADDITIONAL CHARGE 1	
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME			DELAY TIME	ADDITIONAL CHARGE 2	
			STANS			GRAND TOTAL \$ 108904	