BIRK PETROLE 874 12 <sup>TH</sup> RD SW	UM WELL CEMENTING	SERVICE TICKET
BURLINGTON,		2/12/12
	FICE, 620-364-6646 - CELL	DATE: 0//7/13
CHARGE TO	Birk Petroleum COUNTY Ct.	CITY
ADDRESS	CITY ST	ZIP
LEASE & WELL	NO. HOZEN H 49 CONTRACTOR	
KIND OF JOB	ment long String SECTWPRG	
DIR. TO LOC		OLD NEW
QUANTITY	MATERIAL USED	SERV. CHG
120sx	Patland Cement	
*		
	BULK CHARGE	
	BULK TRK. MILES	
	PUMP TRK. MILES	
	PLUGS	
	TOTAL	
T.D. 1029	CSG. SET AT 1015	VOLUME
1.D. 102	CSG. SET AT 7010	VOLUME
SIZE HOLE	TBG SET AT	VOLUME
MAX. PRESS	SIZE PIPE 2 7/8"	
PLUG DEPTH	PKER DEPTHPL	UG USED
TIME FINISHED:		
REMARKS:	meet to pipe. Pump Gement	into well. Good
0110.10	minut. Sou wripert.	
NAME		
- 14		

OWNER'S REP.

CEMENTER OR TREATER

802 N. Industrial Rd. P.O. Box 664 Iola, Kansas 66749 Phone: (620) 365-5588

## Payless Concrete Products, Inc.

strength test when water is added at custom NOTICE TO OWNER
Failure of this contractor to pay hose personnel of the complete this contract can result in the limit of the subject of this contract.

SOLD TO BB001

B & B COOPERATIVE VENTURES

58 W TO WAYSIDE RD N 1 1/2 MI

WELL# HAZEN A #50

66655 LE RUY, RS 66857							
TIME	FORMULA	LOAD SIZE	YARDS ORDERED		DRIVER/TRUCK		PLANT/TRANSACTION #
10 33 50				% CAL	JH	% AIR	-
	IELL	12.00 yd	12.00 yd	0.00	31	0.00	COFCO
DATE		LOAD #	YARDS DEL.	BATCH#	WATER TRIM	SLUMP	TICKET NUMBER
	o Date	10	120.00 yd	*			
01-17-13	oday	L. Lad	12.00 yd	23099	G/yd 0.0	4.00 in -	33394

WARNING

IRRITATING TO THE SKIN AND EYES
Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY
CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of
Contact With Skin or Eyes, Flush Thoroughly With Water, If Irritation Persists, Get Medical
Attention. KEEP CHILDREN AWAY.

CONCRETE IS a PERISHABLE COMMODITY and BECOMES the PROPERTY of the PURCHASER UPON LEAVING the PLANT. ANY. CHANGES OR CANCELLATION of ORIGINAL INSTRUCTIONS MUST be TELEPHONED to the OFFICE BEFORE LOADING STARTS.

The undersigned promises to pay all costs, including reasonable attorneys' fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 24% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$25 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks. Excess Delay Time Charged @ \$50/HR.

PROPERTY DAMAGE RELEASE
(TO BE SIGNED FELLIVERY TO BE MADE INSIDE CURB LINE)

Dear Customer: The driver of this truck in presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if higheose the material in this load where you desire it, it is our wish to help you'lin eyery way that we can, but in order to did this order to it in the driver is requesting that you sign this RELEASE relieving him and this supplier form any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sickeyskis, driveways, curbs, etc., by the delivery of this material, and that you also agree to help him remove mud from the wheels of his welfules so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisin out of delivery of this order.

**Excessive Water is Detrimental to Concrete Performance** H<sub>2</sub>0 Added By Request/Authorized By

WEIGHMASTER

QUANTITY	CODE	DECODIDATION	- / /		
GOANTITI	CODE	DESCRIPTION	/	UNIT PRICE	EXTENDED PRICE
12.00 12.00 2.50	WELL MIX&HAUL TRUCKING	WELL (10 MIXING & TRUCKING	12.00 12.00 2.50	51.00 25.00 50.00	612.00 300.00 125.00

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	DELAY EXPLANATION/CYLINDER TEST TAKEN	TIME ALLOWED	
3124	2150		JOB NOT READY     6. TRUCK BROKE DOWN     7. ACCIDENT     TRUCK AHEAD ON JOB     8. CITATION	5	ubTotal \$ 1037.00 ax % 6.300 65.33
LEFT PLANT	ARRIVED JOB	START UNLOADING	CONTRACTOR BROKE DOWN     OTHER     ADDED WATER	TIME DUE	otal \$ 1102.33
12:52	1:20			0	rder \$ 1102.33
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME		DELAY TIME	ADDITIONAL CHARGE 2
2.5					GRAND TOTAL
					GRAND TOTAL