DRILLERS LOG

Company: Mark Morrison

Farm: Kimberlin
Well No: k-9
API: 15-205-28151-00-00
Surface Pipe: 40'

Contractor: EK Energy LLC
License# 33977
County: ~~Allen~~ Wilson
Sec: 3 TWP: 27 R 16 E
Location: 743 FSL
Location: 1719 FWL
Spot: SE-NW-SE-SW

Thickness	Formation	Depth	Remarks
	SOIL & CLAY	3	Drilled 97/8 Hole Set 7"
37	LIME	40	Drilled 5 7/8 HOLE
112	SHALE	152	
23	LIME	175	
41	SHALE	216	Started 5/20/2013
32	LIME	248	Finished 5/21/2013
70	SHALE	318	
10	LIME	328	
18	SHALE	346	T.D. Hole 1010
173	LIME	519	T.D. PIPE 983.40
112	SHALE	631	OIL PATCH PIPE TALLEY
12	LIME	643	
76	SHALE	719	
31	LIME	750	
29	SHALE	779	
16	LIME	795	
7	SHALE	802	
4	LIME	806	
129	SHALE	935	
8	OIL SAND	943	
1	COAL	944	
TD	SHALE	1010	