

Saman Sharifai

Petroleum Geologist

API #15-051-20522

API #15-051-26522

GEOLOGIST'S REPORT

DRILLING TIME AND SAMPLE LOG

COMPANY	Murfin Drilling Co., Inc.	ELEVATIONS
LEASE	Rankin #1-33	KB 2303'
FIELD	Rankin	DF
LOCATION	330' FSL & 2050' TEL	GL 2298'
SEC	33 TWSP	Measurements by All
CONTRACTOR	Murfin Drilling #16	From Kelly Bushing
SPUD	05/05/13	CASE
RTD	4051'	conductor
MUD UP	2928'	surface 8.58" at 2177'
SAMPLES SAVED FROM	3200'	NA
DRILLING TIME KEPT FROM	3200'	ELECTRICAL SURVEYS
SAMPLES EXAMINED FROM	3200'	CND: DIL: MEL: Sonic
GEOLOGICAL SUPERVISION FROM	2900'	Pioneer Pipeline
REFERENCE WELL	Chief Drilling, Rankin #2-33	

REMARKS Due to very fair shows of oil in multiple pay zones and negative DST results, it is recommended and agreed upon by all parties that this well shall be plugged and abandoned.

Respectfully Submitted,

Saman Sharifai
Petroleum Geologist

*Tops have been adjusted to electric logs

