COLT ENERGY, INC.

Plugging Report

10/11/2013

Pauling Scott #WI-8

Section 33-T15S-R20E Franklin Co., KS API #15-059-24184

10/11/2013

W & W Production Company (operator license #5491), rigged up to the 1" tubing plugging string, broke circulation, circulated down last 2 joints to the total depth of 765' (taken from the MIT sheet). Pumped in cement, circulated same to surface, pulled out 1", "topped off" well with cement, rigged down and moved over to the #WI-11.

Pauling Scott #WI-11

Section 33-T15S-R20E Franklin Co., KS API #15-059-24200

10/11/2013

W & W plumbed up to the 1" tubing plugging string, broke circulation, circulated down last half of last joint to the total depth of 769' (taken from the MIT sheet). Pumped in cement, circulated same to surface, pulled out 1", "topped off" well with cement, connected up to the 2 7/8" casing, pressured up on same, rigged down and left location.

Note: Levi Short, with the KCC, was on location for both the above wells and "approved" same.

End Report

Rex R. Ashlock

For: Colt Energy, Inc.

W & W Production Company

1150 Highway 39

Chanute, Kansas 66720-5215

Mobile: 620-431-5970

Phone: Office/Home 620-431-4137

Invoice

DATE	INVOICE NO.		
10/18/2013	46870		

BILL TO	
Colt Energy C/O Rex Ashlock PO Box 388 1112 Rhode Island Rd. Iola, Kansas 66749	

Plug Well WI-8 Pauline Scott
Franklin County, Kansas

SERVICED	ITEM	DESCRIPTION	QTY	RATE	AMOUNT
SERVICED 10/11/2013	Pump Truck Cement Vacuum truck	Pump Charge For plugging Haul water 143 000 267 103	1 23 3	500.00 10.00	500.00T 230.00T 240.00T
			Sales T	ax (7.65%)	\$74.21
			Total		\$1,044.21

Fax # Fed. I.D. 48-0843238
620-431-3183 carolwimsett4@yahoo.com

OCT 2 1 REC'D

3hr- 256-209-333 COLT ENERGY, INC. — OIL OPERATION

WELL PULLING RECORD Date 10 - 7-13
Lease Name 2. 500770 Well No. 8WI
Reason for Pulling plugging in s
Type of Pump Removed
Special Equip. Removed (Anchors, Checks, etc.)
T.D., SLM Fluid Level from Surface
Well Conditions Seen (Corrosion, Gas, Gyp, Paraffin, Sand, etc.)
Chemical Treatment (Kind and Amount)
Type of Pump Run In
Special Equipment (Anchors, Checks, etc.) Run In
Additional Information; including jack or other repairs, tubing clamp loose, and oil cleanup. Part 1 plag 5 (Ring to 875 - TD) H well 765 - Wash clears rest y when we Cement
ρ

COLT ENERGY, INC. — OIL OPERATION

WELL PULLING RECORD Date 10 -11-13
Lease Name #: SCOTTC Well No 8 - WI _
Reason for Pulling DIUGGING
Type of Pump Removed
Special Equip. Removed (Anchors, Checks, etc.)
T.D., SLM Fluid Level from Surface
Well Conditions Seen (Corrosion, Gas, Gyp, Paraffin, Sand, etc.)
Chemical Treatment (Kind and Amount)
Type of Pump Run In
Special Equipment (Anchors, Checks, etc.) Run In
Additional Information; including jack or other repairs, tubing clamp loose, and oil cleanup. 1956 / 40 765 - w full 2 with coment - Pull life 70 P & FF