EDWARD E BIR 302 SOUTH 16TH BURLINGTON, I 620-364-1311 - OI CHARGE TO ADDRESS LEASE & WELL, I KIND OF JOB DIR. TO LOC.	WELL CEMENTING  KS 66839  FFICE, 620-364-6719 - CELL  COUNTY F. DATE: 07/24  CITY ST ZIP	4/13		
QUANTITY	MATERIAL USED	SERV. CHG		
120 St	Portland Cement			
**				
	BULK CHARGE			
	BULK TRK. MILES			
	PUMP TRK. MILES			
	PLUGS			
	TOTAL			
T.D. 10/6	CSG. SET AT 1002 VOLUME			
SIZE HOLE 6	TBG SET AT			
MAX. PRESS	SIZE PIPE 2 7/8 "			
PLUG DEPTH	PKER DEPTH PLUG USED			
TIME FINISHED:	anect to gipe Pump Cement into well-	Good circ.		
NAME	Edurand Birk	,		

CEMENTER OR TREATER

802 N. Industrial Rd. P.O. Box 664 Iola, Kansas 66749 Phone: (620) 365-5588



CONDITIONS

Concerns to be delivered to the nearest accessible point over passable road, under thork own power. Due to delivery at owner's or intermediary's direction, as the content of the content of

HAMATO:

B & B COOPERATIVE VENTURES 900 S. FOURTH ST.

> BURLINGTON KS 66839

SHIP TO: BI/E. LEHMA B & B COOP, VENTURES/BIRK DIL 58-WATO BRIDERWOOD RD W E-MI TO WOLVS STH RD W 174 44 SON 6 LE ROY, KS 66857

TIME	FORMULA -	LOAD SIZE	YARDS ORDERED	× 001	DRIVER/TRUCK	4 016	PLANT/TRANSACTION #
08:10:44a	WELL	12.00 yd	12.00 yd	0.00	is in	0.00	
DATE	To Date	LOAD#	1 YARDS DEL	BATCH#	WATER TRIM	SLUMP	TICKET NUMBER
07-24-13	Today	1	12.00 yd	24627	G/yd 0.0	4.00 in	34605

WARNING

IRRITATING TO THE SKIN AND EYES
Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY
CAUSE BURNS: Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of
Contact With Skin or Eyes, Flush Thoroughly With Water, If Irritation Persists, Get Medical
Attention. KEEP CHILDREN AWAY.

CONCRETE Is a PERISHABLE COMMODITY and BECOMES the PROPERTY of the PURCHASER UPON LEAVING the PLANT. ANY CHANGES OR CANCELLATION of ORIGINAL INSTRUCTIONS MUST be TELEPHONED to the OFFICE BEFORE LOADING STARTS.

The undersigned promises to pay all costs, including reasonable attorneys' fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 24% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$25 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks Excess Delay Time Charged @ \$50/HR.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY TO BE MADE INSIDE CURB LINE)

(TO BE SIGNED IF DELIVERY TO BE MADE INSIDE CURB LINE)
Dear Customer-The driver of this truck in presenting this RELEASE to
you for your signature is of the opinion that the size and weight of his
truck may possibly cause damage to the premises and/or adjacent
property. If il places the material in this load where you desire, lik it is
our wish to help you in every way that we can, but in order to do this
the driver is requesting that you sign his RELEASE relieving him and
this supplier from any responsibility from any damage that may occur
to the premises and/or adjacent property, buildings, sidewise,
driveways, ourbs, etc., by the delivery of this material, and that you
also agree to help him remove must form the wheels of his vehicle so
that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver
of this truck and this supplier for any and all damage to the premises
and/or adjacent property which may be claimed by anyone to have
arisin out of delivery of this order.

**Excessive Water is Detrimental to Concrete Performance** H<sub>2</sub>0 Added By Request/Authorized By

WEIGHMASTER

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

QUANTITY CODE DESCRIPTION 1 UNIT PRICE EXTENDED PRICE 1/2.00 12.00 WELL WELL (10 SACKS WER UNIT) 250 2.25 TRUCKING TRUCKING CHARGE 2.50 12.00 MIXSHAUL MIXING & HALLING 12.00

1 412	TIME ALLOWED	DELAY EXPLANATION/CYLINDER TEST TAKEN	FINISH UNLOADING	LEFT JOB	RETURNED TO PLANT
P 1		JOB NOT READY     6. TRUCK BROKE DOWN     7. ACCIDENT     3. TRUCK AHEAD ON JOB     8. CITATION		15:11	10:44
]	TIME DUE	CONTRACTOR BROKE DOWN     OTHER     ADDED WATER	START UNLOADING	ARRIVED JOB	LEFT PLANT
ADDITIONAL CHARGE A LASTO	· · · · · · · · · · · · · · · · · · ·			GAN	3/0/2
ADDITIONAL CHARGE I				7000	0.00
ADDITIONAL CHARGE 2	DELAY TIME		UNLOADING TIME	TOTAL AT JOB	TOTAL ROUND TRIP
					0-6
GRAND TOTAL					0.20