

# SUNFLOWER WELL SERVICE, INC.

2185

COMPLETION—WORKOVER—ROD & TUBING SERVICE  
408 N. 4TH STREET, P.O. BOX 341, CANTON, KS 67428

Company Treks AEC  
Lease Lawrence Well 1-17  
Unit 3 Oper CL Prod. well New well Inj. well

DATE	WORK DONE	HRS.	AMOUNT
10-25-13	Moved to location Rigged up. Ran bailer found T.D @ 3500 ft. Dumped 150 gals of sand. Had surface dug out. Rigged up to pull casing. Pull slip's. Ran dump bailer found sand @ 3359 ft. dump 5 s/s of g/m on sand. Shut down.		
	Rxc	8	
10-28-13	Rip casing @ 2400 ft work casing. Rip @ 2200 ft work free. Pulled casing. Bail casing down to 300 ft. fill to surface with g/m. Rigged down.		
	Rxc	8	
<b>EXTRA EQUIPMENT &amp; SUPPLIES</b>		<b>HRS.</b>	<b>AMOUNT</b>
Power tongs			
Kero. & Paint			
Swab Cups			
Other:			
		SUB TOTAL	
		TAX	
		TOTAL	

### WELL RECORD

Pulled	RODS	Ran	Pulled	TUBING	Ran
	1			3"	
	7/8			2 1/4	
	3/4			2	
	5/8			subs	
	subs			subs	
	subs			barrell	
	pump			sn	
				perf.	
				ma	

# CONCRETE PRODUCTS, INC.

HILLSBORO, KANSAS  
620/947-5921

209 N. CEDAR

MARION, KANSAS  
620/382-3311

48775

DATE 10/29/13

TERMS: NOT LATER THAN 10TH OF FOLLOWING MONTH

SOLD TO SUNFLOWER Well Service

DELIVER TO 45 Canton Eisenhower

MAILING ADDRESS 1 West 1/4 S

TRUCK NO.

DRIVER

QTY.	DESCRIPTION	PRICE	TOTAL
<u>6yd</u>	<u>Slurry Mix</u>		

EXTRA WATER ADDED \_\_\_\_\_ GALLONS (by request of customer)

### RECEIPT AND RELEASE

One Hour Free Time Will Be Allowed For Unloading In Consideration of your making delivery back of the Street Curb Line, I agree to be responsible for all damages done to sidewalks, grounds, or otherwise.

RECEIVED THE ABOVE MATERIAL IN GOOD CONDITION.

SIGN HERE \_\_\_\_\_

PERIODIC RATE OF 1 1/2% PER MONTH FINANCE CHARGE  
WILL BE APPLIED TO PAST DUE ACCOUNTS (18% ANNUAL RATE)

Reprint from Baker Bros. Printing Co. - Hillsboro, KS 67053



# Daily Workover Report

<b>Well:</b> Lawrence #1-17	<b>Report #:</b> 2	<b>Date:</b> 29-Oct-13
<b>Location:</b>	<b>AFE:</b>	<b>Daily \$:</b> 300
<b>Rig:</b> Sunflower	<b>KB:</b> 1,557	<b>Cum \$:</b> 300
<b>Supv:</b> Thad Starr	<b>GL:</b> 1,548	<b>AFE \$:</b> 0

<b>Next Planned Operation:</b>	Pipe Tally	Material Transfer
--------------------------------	------------	-------------------

From	To	Hrs:Min	Detail Operations Report
7:00 AM	5:30 PM	10:30	Ran in casing knife to 2300' and worked casing loose and start pulling 5 1/2" casing. Pulled 51 joints of casing. Ran bailer and found fluid at 300' went got wood plug and set it at 270' and put 6 pails sand on plug and then 6 yards cement and filled to top of surface casing.
			Witnessed by Hunter Clark with KCC district 1
			Well plugged in lieu of recovered casing.
<b>Total</b>		<b>10:30</b>	

Cost Estimate	Daily \$	Cum \$	AFE \$	Comments
9561 Pulling Unit / Rig		0	0	
9579 Supervision	300	300	0	Thad Starr
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
0		0	0	
<b>Total</b>	<b>300</b>	<b>300</b>	<b>0</b>	



## Daily Workover Report

<b>Well:</b> Lawrence #1-17	<b>Report #:</b> 1	<b>Date:</b> 28-Oct-13
<b>Location:</b>	<b>AFE:</b>	<b>Daily \$:</b> 0
<b>Rig:</b> Sunflower	<b>KB:</b> 1,557	<b>Cum \$:</b> 0
<b>Supv:</b> Thad Starr	<b>GL:</b> 1,548	<b>AFE \$:</b> 0

<b>Next Planned Operation:</b>	Pull casing and pump top plug	<u>Swab Report</u>	<u>Wellbore Diagram</u>	<u>Pipe Tally</u>	<u>Material Transfer</u>
--------------------------------	-------------------------------	--------------------	-------------------------	-------------------	--------------------------

From	To	Hrs:Min	Detail Operations Report
7:00 AM			Sanded off formation and put 2 sx cement top of sand
<b>Total</b>		<b>0:00</b>	

Cost Estimate	Daily \$	Cum \$	AFE \$	Comments
9561 Pulling Unit / Rig	0	0		
9579 Supervision	0	0		Thad Starr
	0	0		
	0	0		
	0	0		
	0	0		
	0	0		
	0	0		
	0	0		
	0	0		
	0	0		
	0	0		
	0	0		
	0	0		
	0	0		
	0	0		
<b>Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	