



TRILOBITE TESTING INC.

1515 Commerce Parkway • Hays, Kansas 67601

Test Ticket

NO. 51829

Well Name & No. Bookstore #3 Test No. 1 Date 12-16-13
 Company Jones Oil LLC. Elevation 1963 KB 1959 GL
 Address 112 N. Gray St. St. John, KS 67576-1923
 Co. Rep / Geo. Keaton Jones Rig Petromark
 Location: Sec. 2 Twp. 24s. Rge. 14w. Co. Stafford State KS

Interval Tested 3636-3656 Zone Tested Lansing "B"
 Anchor Length 20 Drill Pipe Run 3494 Mud Wt. 9.0
 Top Packer Depth 3631 Drill Collars Run 117 Vis 65
 Bottom Packer Depth 3636 Wt. Pipe Run Ø WL 8.0
 Total Depth 3656 Chlorides 5000 ppm System LCM Ø

Blow Description IFI Strong blow. BOB @ 2min. No GTS

ISI: No blow.

FF: Strong blow. BOB immed. GTS @ 57min. TSTM.

FSI: Weak 1" bb.

Rec	Feet of	%gas	%oil	%water	%mud
<u>90</u>	<u>OWGCM</u>	<u>20</u>	<u>2</u>	<u>45</u>	<u>63</u>
<u>120</u>	<u>SLI ocmw</u>	<u>2</u>	<u>68</u>	<u>30</u>	

Rec Total 210 BHT 111 Gravity N/C API RW .3 @ 40 ° F Chlorides 43000 ppm

(A) Initial Hydrostatic 1869 Test 2100 T-On Location
 (B) First Initial Flow 23 Jars 2259 T-Started
 (C) First Final Flow 56 Safety Joint 2111 T-Open
 (D) Initial Shut-In 1048 Circ Sub 0426 T-Pulled
 (E) Second Initial Flow 48 Hourly Standby 0641 T-Out
 (F) Second Final Flow 94 Mileage 52 Comments
 (G) Final Shut-In 1032 Sampler
 (H) Final Hydrostatic 1770 Straddle Ruined Shale Packer
 Shale Packer Ruined Packer
 Extra Packer Extra Copies
 Extra Recorder
 Day Standby
 Accessibility

Initial Open 30
 Initial Shut-In 45
 Final Flow 60
 Final Shut-In 60
 Sub Total
 Total
 MP/DST Disc't

Approved By Keaton Jones Our Representative Ryan Reynolds

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.