



# TRILOBITE TESTING INC.

1515 Commerce Parkway • Hays, Kansas 67601

## Test Ticket

NO. 51831

Well Name & No. Bookstore #3 Test No. 3 Date 12-18-13  
 Company Jones Oil LLC Elevation 1963 KB 1958 GL  
 Address 112 N. Gray St. St. John, KS 67576-1923  
 Co. Rep / Geo. Keaton Jones/Jeff Burke Rig Petromark #2  
 Location: Sec. 2 Twp. 24s. Rge. 14w. Co. Stafford State KS

Interval Tested 3742-3776 Zone Tested Kans. "H-I"  
 Anchor Length 34 Drill Pipe Run 3621 Mud Wt. 9.2  
 Top Packer Depth 3737 Drill Collars Run 117 Vis 54  
 Bottom Packer Depth 3742 Wt. Pipe Run Ø WL 10.4  
 Total Depth 3776 Chlorides 8000 ppm System LCM 9

Blow Description IFI: Strong blow, BOB @ 1 1/2 min. No GTS.  
ISI: Weak 1/4" BB.  
FFI: Strong blow, BOB immed. No GTS.  
FSI: Good 6" BB, GTS on BB

Rec	Feet of	%gas	%oil	%water	%mud
<u>90</u>	<u>WOGM</u>	<u>28</u>	<u>25</u>	<u>20</u>	<u>27</u>
<u>120</u>	<u>MCOGW</u>	<u>25</u>	<u>25</u>	<u>43</u>	<u>7</u>
<u>80</u>	<u>OGMLW</u>	<u>10</u>	<u>4</u>	<u>63</u>	<u>23</u>
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 270 BHT 111 Gravity N/L API RW .22 @ 70 °F Chlorides 32000 ppm

(A) Initial Hydrostatic 1942  Test 0815 T-On Location  
 (B) First Initial Flow 31  Jars 0830 T-Started  
 (C) First Final Flow 65  Safety Joint 1024 T-Open  
 (D) Initial Shut-In 1088  Circ Sub 1336 T-Pulled  
 (E) Second Initial Flow 63  Hourly Standby 1540 T-Out  
 (F) Second Final Flow 112  Mileage 52 Comments  
 (G) Final Shut-In 1079  Sampler  
 (H) Final Hydrostatic 1835  Straddle  Ruined Shale Packer  
 Shale Packer  Ruined Packer  
 Extra Packer  Extra Copies

Initial Open 30  Extra Recorder  
 Initial Shut-In 45  Day Standby  
 Final Flow 60  Accessibility  
 Final Shut-In 60  Sub Total  
 Sub Total \_\_\_\_\_ MP/DST Disc't \_\_\_\_\_

Approved By \_\_\_\_\_ Our Representative Ryan Reynolds

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.