JAMES C. MUSGROVE

Petroleum Geologist 212 Main Street P.O. Box 215 Claflin, KS 67525

Office (620) 588-4250

Res. Claflin (620) 587-3444

Mai Oil Operations
Martin Dietz #1
SW-NW-SE-NW (1840' FNL & 1375' FWL)
Section 9-15s-14w
Russell County, Kansas
Page 1

5 1/2" Production Casing Set

Contractor:

Southwind Drilling Co. (Rig #3)

Commenced:

November 29, 2013

Completed:

December 4, 2013

Elevation:

1839' K.B; 1837' D.F; 1831' G.L.

Casing program:

Surface; 8 5/8" @ 477'

Production; 5 1/2" @ 3357'

Sample:

Samples saved and examined 2300' to the Rotary Total Depth.

Drilling time:

One (1) foot drilling time recorded and kept 2300 ft. to the Rotary Total

Depth.

Measurements:

All depths measured from the Kelly Bushing.

Drill Stem Tests:

There were three (3) Drill Stem Tests ran by Trilobite Testing Co.

Electric Log:

By Nabors; Dual Induction, Compensated Density/Neutron and Micro Log.

Formation	Log Depth	Sub-Sea Datum
Anhydrite	824	-1015
Base Anhydrite	857	+982
Grand Haven	2392	-553
1 st Tarkio Sand	2403	-564
Dover	2418	-579
2 nd Tarkio Sand	2428	-589
Tarkio Lime	2465	-626
Elmont	2526	-687
Howard	2664	-825
Topeka	2728	-889
Heebner	2959	-1120
Toronto	2976	-1137
Lansing	3018	-1179
Base Kansas City	3226	-1387
Conglomerate	3250	-1411
Arbuckle	3271	-1432
Rotary Total Depth	3365	-1526
Log Total Depth	3358	-1519
/All tone and zance	corrected to Electric Log !	macauramenta)

(All tops and zones corrected to Electric Log measurements).

SAMPLE ANALYSIS, SHOWS OF OIL, TESTING DATA, ETC.

Mai Oil Operations Martin Dietz #1 SW-NW-SE-NW (1840' FNL & 1375' FWL) Section 9-15s-14w Russell County, Kansas Page 2

1ST TARKIO SAND SECTION

2403-2413

Sand; gray, grayish green, very fine grained, silty, poorly developed, no shows.

% oil, 30% gas, 10% mud, 5% mud)

375' very heavily oil and gas out thin watery mu

2ND TARKIO SAND SECTION

2428-2442'

Sand; gray, very fined grained, sub rounded, friable, fair intergranular porosity, micaceous, few shaley, fair stain and saturation, fair show of free oil and faint odor in fresh samples.

Drill Stem Test #1

2404-2460' (Log corrected 2397-2453)

Times:

30-30-45-45 inely crystalline, chalky

Blow:

Strong

Recovery:

1220' gas in pipe

375' very heavily oil and gas cut thin watery mud

or (55% oil, 30% gas, 10% mud, 5% mud)

Pressures: ISIP

ISIP 715 psi FSIP 706 psi IFP 42-128 psi FFP 147-231 psi HSH 1179-1105 psi

TOPEKA SECTION

2803-2814'

Limestone; white, few fossiliferous, chalky, poor visible porosity, trace brown stain, no show of free oil and no odor.

2896-2930'

Limestone; tan, finely crystalline, chalky, poor visible porosity, trace poor stain, no show of free oil and no odor in fresh

samples.

TORONTO SECTION

2976-2990'

Limestone; tan, cream, finely crystalline, chalky, scattered porosity, poorly developed, brown spotty stain, show of free oil and faint odor in fresh samples.

LANSING SECTION

3018-3026'

Limestone; tan, cream, finely crystalline, poor scattered porosity, light brown stain, trace of free oil and questionable odor.

3043-3050'

Limestone; tan, finely crystalline, scattered sub-oomoldic type porosity, few cherty, trace stain, weak show of free oil and no odor in fresh samples.

3061-3071'

Limestone; tan, finely crystalline, oomoldic, good oomoldic porosity, fair stain, good show of free oil and faint odor in fresh samples.

Mai Oil Operations Martin Dietz #1 SW-NW-SE-NW (1840' FNL & 1375' FWL) Section 9-15s-14w Russell County, Kansas Page 3

Drill Stem Test #2

3034-3084' (Log corrected 3027-3077)

Times:

30-30-45-45

Blow:

Weak shows

Recovery: 10' mud

Pressures: ISIP

56 psi psi FSIP 55 ight IFP 14-16 psi **FFP** 16-18 psi

HSH 1554-1482 psi

3096-3106'

Limestone; tan, finely crystalline, poorly developed porosity, chalky, trace poor stain, trace of free oil and no odor in fresh samples.

3113-3130'

Limestone; tan, finely crystalline, oomoldic, poor to fair oomoldic porosity, trace stain, show of free oil and no odor in fresh samples.

3142-3155'

Limestone; cream, tan, finely crystalline, slightly cherty, scattered

porosity, no shows.

3162-3177

Limestone; cream, finely crystalline, few fossiliferous, poor

porosity, no shows.

3188-3196'

Limestone; tan, brown, finely crystalline, slightly cherty, trace

light brown stain, no free oil and no odor.

3201-3210'

Limestone; white, oolitic, chalky, poorly developed porosity, chalky, no shows.

CONGLOMERATE SECTION

3250-3271'

Varied colored chert in matrix of red/green/gray shales.

ARBUCKLE SECTION

3271-3290'

Dolomite; white, finely crystalline, granular, sucrosic, poor scattered porosity, no shows.

3290-3299'

Dolomite: white, finely crystalline, fair to good intercrystalline, porosity, poor stain, trace of free oil and no odor in fresh

samples.

Mai Oil Operations Martin Dietz #1 SW-NW-SE-NW (1840' FNL & 1375' FWL) Section 9-15s-14w Russell County, Kansas Page 4

Drill Stem Test #3

3232-3310' (Log corrected 3225-3303)

Times:

30-30-30-30

Blow:

Strong

Recovery:

2340' water

Pressures: ISIP

ISIP 1096

psi

FSIP 1101

psi

IFP 723-935

pai

FFP 935-1085

psi psi

HSH 1771-1600

psi

3299-3310'

Dolomite; white, finely crystalline, dense, poor porosity.

3310-3330'

Dolomite; as above, increase in porosity, no show.

3330-3353'

Dolomite; white, rose/pink, finely crystalline, granular in part, no

shows.

3353-3358'

Dolomite; white, sandy, poor porosity, no shows.

Rotary Total Depth

3365

Log Total Depth

3358

C. MUSG

Recommendations: 5 1/2" production casing was set and cemented in the Martin Dietz #1.

Wyall Urban

Respectfully submitted;

James C. Musgrove and

Wyatt Urban,

Petroleum Geologists

poor perosity,