



**Cement Report**

Customer <b>Raydon Exploration</b>	Lease No.	Date <b>1/25/14</b>
Lease <b>Buffalo</b>	Well # <b>1-27</b>	Service Receipt
Casing	Depth	County <b>Finney</b> State <b>KS</b>
Job Type <b>PTA</b>	Formation	Legal Description

Pipe Data		Perforating Data		Cement Data
Casing size	Tubing Size	Shots/Ft		Lead <b>260SX</b> PP @ <b>135#</b>  <b>1.50</b> <b>7.50</b> Tail in
Depth	Depth	From	To	
Volume	Volume	From	To	
Max Press	Max Press	From	To	
Well Connection <b>Drill Pipe</b>	Annulus Vol.	From	To	
Plug Depth	Packer Depth	From	To	

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
17:00					on loc, spot & R.O., safety netg
20:32		210	10	3	H2O
20:35		230	13.36	3.4	start mixing 50sx @ 1860'
20:40		0	2	3.4	H2O
20:40		170	21	5	Mud
21:03		210	10	3	H2O
21:06		230	13.36	3.4	Mix 50sx @ <del>1620</del> 1620'
21:10		0	2	3.4	H2O
21:10		140	17	5	Mud
21:44		170	10	3.8	H2O
21:47		170	13.36	3.8	Mix 50sx @ <del>910</del> 910'
21:52		0	2	4	H2O
22:56		130	10.6	5	Mix 40sx @ 350'
23:01		0	1	5	H2O
23:10		60	5.4	4	Plug @ 60'
23:18					Plug @ R & M Job Complete

Service Units	<b>74939</b>	<b>372233972</b>	<b>304631976</b>		
Driver Names	<b>Celinz</b>	<b>T. Marcellus</b>	<b>F. Ampeval</b>		

**Andrew**  
Customer Representative

**Ferry Bennett**  
Station Manager

**Chal**  
Cementer