



**Cement Report**

Customer <i>Huntington Energy</i>		Lease No.		Date <i>03-10-14</i>	
Lease <i>Stanley</i>		Well # <i>2</i>		Service Receipt <i>1717-04899-A</i>	
Casing <i>8 5/8"</i>		Depth <i>1720'</i>		County <i>SEWARD</i> State <i>K5</i>	
Job Type		Formation		Legal Description	
<b>Pipe Data</b>			<b>Perforating Data</b>		<b>Cement Data</b>
Casing size <i>8 5/8"</i>		Tubing Size		Shots/Ft	
Depth <i>1720'</i>		Depth		From	To
Volume		Volume		From	To
Max Press		Max Press		From	To
Well Connection		Annulus Vol.		From	To
Plug Depth <i>1679'</i>		Packer Depth		From	To
Lead <i>4 1/2" sks</i> <i>1" ACum' Blaw</i> <i>2.95" Coult. sk 18.1 gal/sk</i> <i>3" Coult. 2" ab/LA-1</i> <i>1/4" Polyflake</i>					
Tail in <i>150 sks</i> <i>Premium Plus Cement</i> <i>3" Coult. 2</i> <i>1/4" Polyflake</i>					
Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
<i>2000</i>					<i>Called out 03-09-14</i>
					<i>03-10-14</i>
<i>2400</i>					<i>On Location Safety Meeting</i>
					<i>03-10-14</i>
<i>0040</i>					<i>Test Lines</i>
<i>0050</i>			<i>07</i>	<i>4</i>	<i>Pump Water ahead</i>
<i>0100</i>	<i>100</i>		<i>218</i>	<i>6.5</i>	<i>Mix &amp; Pump Lead Cement</i>
<i>0200</i>			<i>358</i>	<i>4</i>	<i>Mix &amp; Pump Tail Cement</i>
					<i>Drop Top Plug</i>
					<i>Wash up on Plug</i>
<i>0210</i>			<i>107</i>	<i>4</i>	<i>Displace</i>
<i>0255</i>	<i>600</i>				<i>Land Plug</i>
					<i>Close heads manifold in</i>
					<i>Back up</i>
					<i>Job Completed</i>
Service Units	<i>21955</i>	<i>38117-19919</i>	<i>30464-31547</i>	<i>30463-19561</i>	
Driver Names	<i>Rogen</i>	<i>Cabel</i>	<i>Santiago</i>	<i>Rivalo</i>	

*Wayne Cook*  
Customer Representative

*Tony Bennett*  
Station Manager

*Rogen Brown*  
Cementer