

EDWARD E BIRK
302 SOUTH 16TH
BURLINGTON, KS 66839

SERVICE TICKET
WELL CEMENTING

620-364-1311 - OFFICE, 620-364-6719 - CELL

COUNTY CF DATE: 01/29/14
CITY _____

CHARGE TO Ed Birk

ADDRESS _____ CITY _____ ST _____ ZIP _____

LEASE & WELL NO. Williams #31 CONTRACTOR _____

KIND OF JOB Cement long string SEC _____ TWP _____ RG _____

DIR. TO LOC. _____ OLD NEW

QUANTITY	MATERIAL USED	SERV. CHG
<u>120 SK</u>	<u>Portland Cement</u>	
	BULK CHARGE	
	BULK TRK. MILES	
	PUMP TRK. MILES	
	PLUGS	
	TOTAL	

T.D. 1058' CSG. SET AT 1011' VOLUME _____

SIZE HOLE 6 1/4 TBG SET AT _____ VOLUME _____

MAX. PRESS. _____ SIZE PIPE 2 7/8"

PLUG DEPTH _____ PKER DEPTH _____ PLUG USED _____

TIME FINISHED: _____

REMARKS: Connect to pipe. Pump Cement into well. Good circ.
to surface. Job complete.

NAME _____

Edward Birk

CEMENTER OR TREATER _____

Ed Birk
OWNER'S REP.

Payless Concrete Products, Inc.



Concrete to be delivered to the nearest accessible point over passable road, under truck's own power. Due to delivery at owner's or intermediary's direction, seller assumes no responsibility for damages in any manner to sidewalks, roadways, driveways, buildings, trees, shrubbery, etc., which are at customer's risk. The maximum allotted time for unloading trucks is 5 minutes per yard. A charge will be made for holding trucks longer. This concrete contains correct water contents for strength or mix indicated. We do not assume responsibility for strength test when water is added at customer's request.

Failure of this contractor to pay those persons supplying material or services to complete this contract can result in the filing of a mechanic's lien on the property which is the subject of this contract.

BB0401

58 W TO SW ARKANSAS RD N 2MI TO
SW 600RD (GTH) W 1MI TO YEARLING
RD NW CORNER

KS 66839

WARNING

X

LOAD RECEIVED BY:

X

QUANTITY	CODE	DESCRIPTION	UNIT PRICE	EXTENDED PRICE
12.00	WELL	WELL (10 SACKS PER UNIT)	12.00	
1.00	WC	WINTER CHARGE	1.00	
12.00	MIX&HDL	MIXING AND HAULING	12.00	
2.50	Trucking Charge			
RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	DELAY EXPLANATION/CYLINDER TEST TAKEN	TIME ALLOWED
3:00	4:25		1. JOB NOT READY 2. SLOW POUR OR PUMP 3. TRUCK AHEAD ON JOB 4. CONTRACTOR BROKE DOWN 5. ADDED WATER 6. TRUCK BROKE DOWN 7. ACCIDENT 8. CITATION 9. OTHER	
LEFT PLANT	ARRIVED JOB	START UNLOADING		TIME DUE
2:39	3:15			
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME		DELAY TIME
GRAND TOTAL				