

John Gage
 WELL - KR1 39
 SURFACE PIPE 7"
 PRODUCTION

OPERATOR Utah Oil
 LOCATION Douglas County
 PIPE used SIZE 2 7/8

START DATE 17 Mar 14
 WELL # 15-045-22137-00-00

Thickness	Formation	Comment	Depth	Thickness	Formation	Comment	Depth
33	Soil		33	2	Lime		361
21	Lime		54	3	Shale		364
6	Shale		58	7	Lime		371
10	Lime		68	9	Shale		378
10	Shale		78	3	wht sand		381
16	Lime		94	41	Shale		422
1	Shale		95	3	graysand		425
2	Lime		97	81	Shale		506
13	Shale		110	2	Lime	Soft	508
2	Lime		112	9	Shale	Red Bed	517
14	Shale		126	5	Lime		522
35	Lime		161	12	Shale		534
33	Shale		194	7	Lime		541
13	Lime		207	2	Shale		543
5	Shale		212	5	Lime		548
8	Lime		220	3	Coal		551
14	Shale		234	9	Lime		560
1	Lime		235	5	Shale		575
1	Shale		236	3	Lime		578
2	Lime		238	11	Shale		589
3	Shale		241	8	Lime		597
9	Lime		250	13	Shale		610
20	Shale		270	2	Lime		612
9	Lime		279	6	Shale	Coal	618
1	Shale		280	7	Lime		625
2	Lime		282	2	Shale		627
4	Shale		286	1	wht shale		628
1	Lime		287	2	Lime	oil smell	630
3	Shale		290	1	oil sand	Core point	631
30	Lime		320	1	oil sand	Broken	632
10	Shale		330	1	oil sand		633
22	Lime		352	2	Broken Sand		635
3	Shale		355	2.5	Shale	Sand streaks	637.5
3	Lime		358	13.5	?	Lost Core	651
1	Shale		359	54	Shale	TD	705

* 631-651X Core point 1 core
 * No Barfile *
 Ronnie