

Miami County, KS  
Well: Doherty KR-18  
Lease Owner: KS. Resources

Town Oilfield Service, Inc.  
(913) 837-8400

Commenced Spudding:  
4/29/2014

WELL LOG

Thickness of Strata	Formation	Total Depth
21	Soil-Clay	21
21	Shale	42
21	Lime	63
10	Shale	73
5	Lime	78
38	Shale	116
14	Lime	130
11	Shale	141
26	Lime	167
6	Shale	173
20	Lime	193
3	Shale	196
19	Lime	215
3	Shale	218
3	Shale	221
17	Shale	238
7	Sand	245
11	Sandy Shale	256
74	Shale	330
6	Sandy Shale	336
20	Shale	356
8	Broken Sand	364
12	Sandy Lime	376
3	Sandy Lime	379
7	Sandy Lime	386
2	Sandy Lime	388
2	Sandy Lime	390
1	Broken Sand	391
4	Shale	395
4	Lime	399
1	Shale	400
7	Sandy Lime	407
3	Lime	410
4	Shale	414
3	Sand	417
5	Sandy Shale	423
24	Shale	447
6	Lime	453
4	Sandy Shale	457
10	Shale	467

