



**Operator:**  
Grand Mesa Operating Co.  
Wichita, KS

**Hutson #14-3**

Coffey Co., KS  
10-22S-16E  
API: 031-23897

**Spud Date:** 5/20/2014  
**Surface Casing:** 7.0"  
**Surface Length:** 40.9'  
**Surface Cement:** Consolidated  
**Longstring:**

**Surface Bit:** 11.0"  
**Drill Bit:** 6.25"  
**Longstring:** P&A  
**Longstring Date:**  
**Seat Nipple:**

**Driller's Log**

<b>Top</b>	<b>Bottom</b>	<b>Formation</b>	<b>Comments</b>
0	10	Soil & clay	
10	22	Gravel & Sand	
22	24	Shale	
24	34	Sand	
34	37	Shale	
37	40	Lime	
40	49	Shale	
49	53	Lime	
53	263	Shale	
263	271	Lime	
271	296	Shale	
296	317	Lime	
317	348	Shale	
348	357	Lime	
357	394	Bl. Shale	
394	409	Lime	
409	428	Shale	
428	462	Lime	
462	468	Shale	
468	478	Lime	
478	482	Shale	
482	497	Lime	
497	504	Shale	
504	507	Lime	

Hutson #14-3

507	514	Red Bed	offey Co., KS
514	549	Shale	
549	587	Lime	
587	599	Shale	
599	608	Lime	
608	614	Shale	
614	637	Lime	
637	647	Shale	
647	658	Lime	
658	663	Shale	
663	665	Lime	Base KC
665	841	Shale	Big Shale
841	853	Lime	
853	862	Shale	
862	864	Lime	
864	906	Shale	
906	913	Lime	
913	934	Shale	
934	940	Lime	
940	942	Shale	
942	944	Lime	
944	954	Shale	
954	962	Lime	
962	966	Shale	
966	980	Lime	20'
980	989	Shale	
989	994	Lime	
994	1019	Shale	
1019	1020	Lime	5'
1020	1032	Shale	
1032	1040	Sandy Shale	Poor sand quality, very light oil show for 8", no show in rest
<b>1040</b>		<b>TD</b>	

Coring		
Run	Footage	Rec.
1	1020-1040	20'

P&A through drill pipe with 10 sx. plug at TD, 10 sx at base of KC, fill from 250-surface