1214450

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
May 2011
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Linn Operating, Inc.
License Number: 33999

Operator Address: 600 TRAVIS STE 5100 HOUSTON TX 77002 3018

Contact Person: Shawn Hildreth
Phone Number: (281) 840 - 4234

Permit Number *(API No. if applicable)*: 15-093-21887-00-00
Lease Name: L.B. WILLITS

Source of Waste:

- ☐ Emergency Pit
- ☐ Settling Pit
- ☐ Workover Pit
- ☑ Drilling Pit
- ☐ Burn Pit
- ☐ Haul-off Pit
- ☐ Steel Pit
- ☐ Spill / Escape
- ☐ Dike

Well Number: A4-ATU-29

Source Location (QQQQ): NE - NW - NW - NW

Sec. 5 Twp. 26 R. 38 ☐ East ☑ West

158 Feet from ☑ North / ☐ South Line of Section

574 Feet from ☐ East / ☑ West Line of Section

GPS Location: Lat: _____ (e.g. xx.xxxxx) , Long: _____ (e.g. -xxx.xxxxx)

Datum: ☐ NAD27 ☐ NAD83 ☐ WGS84

County: Kearny

No Waste to be Hauled: ☑ *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: ☐ Fluid ☐ Soil ☐ Mud / Cuttings ☐ Other: _____

Amount of waste: _____ No. of loads _____ Barrels _____ Tons _____ YDS

Destination of waste: ☐ Reserve Pit ☐ Haul Off Pit ☐ Disposal Well ☐ Lease Road ☐ Dike / Berm ☐ Other: _____

If waste is transferred to another reserve pit, is the lease active? ☐ Yes ☐ No

Location of Waste Disposal:

Destination Out of State: ☐ *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: _____

Operator Name: _____ License No.: _____

Lease Name: _____ Sec. _____ Twp. _____ R. _____ ☐ East ☐ West

Docket No./API No.: _____ County: _____

Comments:

After an audit of LINN's approved Intent to Drill and special provisions (if applicable), it was determined an oversight was made to remove fluids from the drilling pit as specified in the approved drilling pit application. Normal protocol was followed. The pit was closed on 11/14/2013. It was closed within 1 yr. of ceasing drilling operations. Measures have since been put in place to ensure these type incidents won't reoccur. LINN is a prudent operator and take full responsibility of our actions. We apologize for any inconvenience this may have caused. Thanks.

Submitted Electronically

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202