



TRILOBITE TESTING INC.

1515 Commerce Parkway • Hays, Kansas 67601

Test Ticket

NO. 59419

Well Name & No. Dawhgan #5 Test No. 1 Date 7-17-14
 Company Mar-Lou Oil Co, LLC Elevation 2342 KB 2333 GL
 Address P.O. Box 218 Wilson, KS 67490
 Co. Rep / Geo. Roger Fisher Rig Southwind 8
 Location: Sec. 20 Twp. 9s Rge. 21w Co. Graham State KS

Interval Tested 3833-3864 Zone Tested Arbuckle
 Anchor Length 31' Drill Pipe Run 3823 Mud Wt. 9
 Top Packer Depth 3828 Drill Collars Run 0 Vis 65
 Bottom Packer Depth 3833 Wt. Pipe Run 0 WL 8
 Total Depth 3864 Chlorides 1,000 ppm System LCM 7#

Blow Description IF- BOB in 30 Sec
ISF No Return
FF BOB in 1 min
FSF No Return

Rec	Feet of	%gas	%oil	%water	%mud
<u>1260'</u>	<u>SMCW</u>		<u>90</u>	<u>10</u>	
<u>819'</u>	<u>WCM</u>		<u>60</u>	<u>40</u>	
<u>411'</u>	<u>USWCM</u>		<u>5</u>	<u>95</u>	
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 2490 BHT 117 Gravity — API RW 127 @ 67 °F Chlorides 3,000 ppm

(A) Initial Hydrostatic <u>1841</u>	<input checked="" type="checkbox"/> Test <u>1150</u>	T-On Location <u>11:02</u>
(B) First Initial Flow <u>573</u>	<input type="checkbox"/> Jars	T-Started <u>11:08</u>
(C) First Final Flow <u>961</u>	<input type="checkbox"/> Safety Joint	T-Open <u>15:23</u>
(D) Initial Shut-In <u>1103</u>	<input type="checkbox"/> Circ Sub	T-Pulled <u>16:53</u>
(E) Second Initial Flow <u>975</u>	<input type="checkbox"/> Hourly Standby	T-Out <u>19:07</u>
(F) Second Final Flow <u>1097</u>	<input checked="" type="checkbox"/> Mileage <u>122 RT 189.10</u>	Comments
(G) Final Shut-In <u>1103</u>	<input type="checkbox"/> Sampler	
(H) Final Hydrostatic <u>1832</u>	<input type="checkbox"/> Straddle	<input type="checkbox"/> Ruined Shale Packer
	<input type="checkbox"/> Shale Packer	<input type="checkbox"/> Ruined Packer
Initial Open <u>15</u>	<input type="checkbox"/> Extra Packer	<input type="checkbox"/> Extra Copies
Initial Shut-In <u>30</u>	<input type="checkbox"/> Extra Recorder	Sub Total <u>0</u>
Final Flow <u>15</u>	<input type="checkbox"/> Day Standby	Total <u>1339.10</u>
Final Shut-In <u>30</u>	<input type="checkbox"/> Accessibility	MP/DST Disc't
	Sub Total <u>1339.10</u>	

Approved By _____ Our Representative Phillip King Thank You

TriLOBITE TESTING INC. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made

Test Ticket

TESTING INC.
1515 Commerce Parkway - Pleasanton, CA 94566

NO.

Client Name	Client Address	Client City	Client State	Client Zip
Client Phone	Client Fax	Client E-mail	Client Website	Client Other
Test No.	Test Date	Test Time	Test Location	Test Status

Test Description	Test Results	Test Comments
Test Method	Test Equipment	Test Personnel
Test Duration	Test Cost	Test Agency

Test Results Summary: [Handwritten notes and data]

Item	Description	Quantity	Unit Price	Total Price
1
2
3

Test Summary: [Handwritten notes and data]

Item	Description	Quantity	Unit Price	Total Price
4
5
6

Test Summary: [Handwritten notes and data]

Test Summary: [Handwritten notes and data]