



BASICSM
ENERGY SERVICES
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61
P.O. Box 8613
Pratt, Kansas 67124
Phone 620-672-1201

FIELD SERVICE TICKET
1718 11007 A

DATE _____ TICKET NO. _____

DATE OF JOB: 6-27-14	DISTRICT: Pratt, KS	NEW WELL <input checked="" type="checkbox"/> OLD WELL <input type="checkbox"/> PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/> CUSTOMER ORDER NO.:							
CUSTOMER: LD Drilling, Inc	LEASE: CHRISTOLIN	WELL NO. 2							
ADDRESS:	COUNTY: Barton	STATE: KS							
CITY:	STATE:	SERVICE CREW: Darin, McGraw, Josh, Scotty							
AUTHORIZED BY:	JOB TYPE: CNW/ Long String								
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	TIME
27283	1						6-27	AM	8:00
77686	1					ARRIVED AT JOB	6-27	AM	8:00
29905	1					START OPERATION	6-27	AM	11:30
19960	1					FINISH OPERATION	6-28	PM	12:30
21010	1					RELEASED	6-28	AM	1:30
						MILES FROM STATION TO WELL			51

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: _____
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CP1006	Common Cement	SK	150		2,400 00
CP103	60/40 Poz	SK	30		360 00
CC111	SSIT	Lb	617		308 50
CC130	C-51	Lb	29		725 00
CC201	Gilsonite	Lb	750		502 50
CF607	Latch Down Plug & Baffle, 5 1/2 (Blue)	ES	1		400 00
CF1251	Auto Fill Float Shoe 5 1/2 (Blue)	ES	1		360 00
CF1651	Turbolizers 5 1/2 (Blue)	ES	6		660 00
CF1901	5 1/2" Basket (Blue)	ES	1		290 00
CF2001	Cement Scrappers Cable Type, 5 1/2	ES	5		375 00
C704	Clymax KCL Substitute	GSI	4		140 00
CG151	Mud Flush	GSI	1,000		1,500 00
E100	Unit Mileage Charge - Pickup	Mi	55		233 75
E101	Heavy Equipment Mileage	Mi	110		770 00
E113	Bulk Delivery	Ton	459		1,010 35
CE204	Depth Charge / 3001-4000	Whis	1		2,160 00
CE240	Blenders & Mixers Service Charge	SK	180		252 00
CE504	Plus Container Utilization Charge	Job	1		250 00
SO03	Service Supervisor, first & his on log	ES	1		175 00
SUB TOTAL					9,782 80

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	% TAX ON \$	
MATERIALS	% TAX ON \$	
TOTAL		

SERVICE REPRESENTATIVE: Doris Kramden	THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: Skiloh
--	---

(WELL OWNER OPERATOR CONTRACTOR OR AGENT)

FIELD SERVICE ORDER NO.

BASIC

energy services, L.P.

TREATMENT REPORT

Customer LD Drilling, Inc	Lease No.	Date 6-27-2014
Lease Chisholm	Well # 2	
Field Order # 11007	Station Prs & 1, KS	Casing 5 1/2
Type Job CNU / Constring	Formation TD-3460	Depth 3453
		County Barton
		State KS
		Legal Description 12-20-12

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP	
5 1/2								5 Min.
Depth 3453	Depth	From	To	Pre Pad	Max			10 Min.
Volume 82	Volume	From	To	Pad	Min			15 Min.
Max Press	Max Press	From	To	Frac	Avg			Annulus Pressure
Well Connection	Annulus Vol.	From	To		HHP Used			Total Load
Plug Depth 3444	Packer Depth	From	To	Flush	Gas Volume			

Customer Representative Shiloh	Station Manager Kevin Gorder	Treater Darin Franklin
--	--	----------------------------------

Service Units	27283	7686	19905	19960	21010				
Driver Names	Darin	McGrew	McGrew	Josh	Josh				

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
8:00am					on location / Safety Meeting
					pipe on bottom & basic circulation
11:30am	300		5	5	5 bbls water
	300		24	5	24 bbls Flush
	300		5	5	5 bbls water
	400		33	5	Mix 150sp common cement - 10% SSC + .2% WCB-1, 5# G. Isonite
					Shut down
					Wash pump & lines
					Release Plug
	200		0	6	Start Displacement
	500		54	6	LiP Pressure
	500		72	3	Slow Rate
11:59	1300		80	3	Bump Plug
					Float die
	100		7	3	Plug Rest hole
					Wash up
12:30pm					Job complete / Darin & crew
					Thank you!!