


FIELD SERVICE ORDER NO.



3406A

## TREATMENT REPORT

Field Order # 10590A		Station Plant	Casing 8 5/8	Depth 3348	County Benton	State KS
Type Job Plug well			Formation CNU		Legal Description 23 19 11	

PIPE DATA		PERFORATING DATA		FLUID USED	TREATMENT RESUME		
Casing Size 2 3/8	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP
Depth 3348	Depth	From	To	Pre Pad	Max		5 Min.
Volume 127	Volume	From	To	Pad	Min		10 Min.
Max Press 500	Max Press	From	To	Frac	Avg		15 Min.
Well Connection 4 1/2	Annulus Vol.	From	To		HHP Used		Annulus Pressure
Plug Depth 3348	Packer Depth	From	To	Flush	Gas Volume		Total Load

Customer Representative			Station Manager			Treater		
Kathy Reardon			Kevin Gentry			Scott		
Service Units	37501	14889	70890					
Driver Names	Scott	198413	71010					
	Casing	Tubing	Josh					

Time	Casing Pressure	Tubing Pressure	Bbbs. Pumped	Rate	Service Log
1:25					On Location Safety Meeting. Pump
1:52	0		12.73	3.5	Pump 50 SKS 60/40 POT at 13.78#
1:58	0		39	7.3	Pump 39 HHS mud
2:03					Shut down Pull pipe up to 558'
3:58	0		6.36	3.2	Pump 25 SKS 60/40 POT at 13.78#
4:06	0		7.9	3.4	Pump 7.9 bbbs H <sub>2</sub> O
4:04					Shut down pull pipe to 350'
4:26	0		16.55	4.3	Pump 6.5 SKS 60/40 POT at 13.78#
4:30	0		5	4.5	Pump 5 bbbs H <sub>2</sub> O
4:32					Shut down pull pipe to 440'
4:51			2.54	2.5	Pump 10 SKS 60/40 POT at 13.78#
4:53					Shut down
5:06			7.64	3	Plug Rest Hole 30SKS 60/40 POT 13.78#
					Job Complete