

# Kepley Well Service, LLC

19245 Ford Road  
Chanute, KS 66720

Date	Invoice #
11/10/2014	50131

## Cement Treatment Report

Multi Plex Resources, LLC  
1300 Rolling Brook Drive, Ste. 605  
Baytown, TX 77521

(x) Landed Plug on Bottom at 750 PSI  
 () Shut in Pressure psi  
 (x) Good Cement Returns  
 () Topped off well with \_\_\_\_\_ sacks  
 (x) Set float shoe

TYPE OF TREATMENT: Production Casing  
 HOLE SIZE: 5 7/8"  
 TOTAL DEPTH: 835

Well Name	Terms	Due Date	
	Net 15 days	12/10/2014	
Service or Product	Qty	Per Foot Pricing/Unit Pricing	Amount
Run and cement 2 7/8" (Casing Depth 826)	835	3.25	2,713.75
Rubber Plug	1	25.39	25.39T
Sales Tax		7.40%	1.88

11.5.14  
 Cannon #CI-1 ✓  
 Allen County  
 Section: 15  
 Township: 26  
 Range: 18

# 71730

**POSTED**  
11-2014

**PAID**  
3698  
11-17-14

Hooked onto 2 7/8" casing. Established circulation with 2.5 barrels of water, GEL, METSO, COTTONSEED ahead, blended 98 sacks of 2% cement, dropped rubber plug, and pumped 4.8 barrels of water

<b>Total</b>	\$2,741.02
<b>Payments/Credits</b>	\$0.00
<b>Balance Due</b>	\$2,741.02