

**Supply Well Service, LLC**

3245 Ford Road  
Chanute, KS 66720

| Date       | Invoice # |
|------------|-----------|
| 11/18/2014 | 50150     |

# Cement Treatment Report

Multi Plex Resources, LLC  
1300 Rolling Brook Drive, Ste. 605  
Baytown, TX 77521

(x) Landed Plug on Bottom at 750 PSI  
 () Shut in Pressure psi  
 (x) Good Cement Returns  
 () Topped off well with \_\_\_\_\_ sacks  
 (x) Set float shoe

TYPE OF TREATMENT: Production Casing  
 HOLE SIZE: 5 7/8"  
 TOTAL DEPTH: 844

| Well Name                                | Terms       | Due Date                      |          |  |
|--|-------------|-------------------------------|----------|--|
|  | Net 15 days | 12/18/2014                    |          |  |
| Service or Product                       | Qty         | Per Foot Pricing/Unit Pricing | Amount   |  |
| Run and cement 2 7/8" (Casing Depth 834) | 844         | 3.25                          | 2,743.00 |  |
| Rubber Plug                              | 1           | 25.39                         | 25.39    |  |
| Sales Tax                                |             | 7.40%                         | 1.88     |  |

11. 14  
Cannon #C-4  
Allen County  
Section: 15  
Township: 26  
Range: 18

# 71730

**POSTED**  
11-20-14

**PAID**  
3704  
11-21-14

Hooked onto 2 7/8" casing. Established circulation with 2 barrels of water, GEL, METSO, COTTONSEED ahead, blended 108 sacks of 2% cement, dropped rubber plug, and pumped 4.8 barrels of water

|                         |            |
|-------------------------|------------|
| <b>Total</b>            | \$2,770.27 |
| <b>Payments/Credits</b> | \$0.00     |
| <b>Balance Due</b>      | \$2,770.27 |