

Kepley Well Service, LLC

19245 Ford Road
Chanute, KS 66720

Date

11/25/2014

Invoice #

50170

Cement Treatment Report

Multi Plex Resources, LLC
1300 Rolling Brook Drive, Ste. 605
Baytown, TX 77521

- (x) Landed Plug on Bottom at 550 PSI
- () Shut in Pressure psi
- (x) Good Cement Returns
- () Topped off well with _____ sacks
- (x) Set float shoe

TYPE OF TREATMENT: Production Casing
HOLE SIZE: 5 5/8"
TOTAL DEPTH: 830

Well Name	Terms	Due Date		
	Net 15 days	12/25/2014		
Service or Product	Qty	Per Foot Pricing/Unit Pricing	Amount	
Run and cement 2 7/8" (Casing Depth 825')	830	3.25	2,697.50	
Rubber Plug	1	25.39	25.39T	
Sales Tax		7.40%	1.88	
<div>11.21.14 Cannon #C5 Allen County Section: 15 Township: 26 Range: 18</div> <div>POSTED 11-20-14</div> <div># 71730 PAID 3712 12-5-14</div>				

Hooked onto 2 7/8" casing. Established circulation with 3.5 barrels of water, 2 GEL, METSO, COTTONSEED ahead, blended 87 sacks of 2% cement, dropped rubber plug, and pumped 4.8 barrels of water

Total	\$2,724.77
Payments/Credits	\$0.00
Balance Due	\$2,724.77