

Kepley Well Service, LLC

19245 Ford Road
Chanute, KS 66720

Date	Invoice #
11/18/2014	50147

Cement Treatment Report

Multi Plex Resources, LLC
1300 Rolling Brook Drive, Ste. 605
Baytown, TX 77521

(x) Landed Plug on Bottom at 800 PSI
 () Shut in Pressure psi
 (x) Good Cement Returns
 () Topped off well with _____ sacks
 (x) Set float shoe

TYPE OF TREATMENT: Production Casing
 HOLE SIZE: 5 7/8"
 TOTAL DEPTH: 820

Well Name	Terms	Due Date		
	Net 15 days	12/18/2014		
Service or Product	Qty	Per Foot Pricing/Unit Pricing	Amount	
Run and cement 2 7/8" (Casing Depth 816)	820	3.25	2,665.00	
Rubber Plug	1	25.39	25.39T	
Sales Tax		7.40%	1.88	

11.13.14
Cannon #C-9
Allen County
Section: 15
Township: 26
Range: 18

A 71730

POSTED
11-20-14

PAID
3704
11-21-2014

Hooked onto 2 7/8" casing. Established circulation with 2 barrels of water, 2 GEL, METSO, COTTONSEED ahead, blended 105 sacks of 2% cement, dropped rubber plug, and pumped 4.8 barrels of water

Total	\$2,692.27
Payments/Credits	\$0.00
Balance Due	\$2,692.27