

**Kepley Well Service, LLC**

19245 Ford Road  
Chanute, KS 66720

Date	Invoice #
11/25/2014	50167

# Cement Treatment Report

Multi Plex Resources, LLC  
1300 Rolling Brook Drive, Ste. 605  
Baytown, TX 77521

(x) Landed Plug on Bottom at 850 PSI  
 () Shut in Pressure psi  
 (x) Good Cement Returns  
 () Topped off well with \_\_\_\_\_ sacks  
 (x) Set float shoe

TYPE OF TREATMENT: Production Casing  
 HOLE SIZE: 5 5/8"  
 TOTAL DEPTH: 825

Well Name	Terms	Due Date		
	Net 15 days	12/25/2014		
Service or Product	Qty	Per Foot Pricing/Unit Pricing	Amount	
Run and Cement 2 7/8" (Casing Depth 816')	825	3.25	2,681.25	
Rubber Plug	1	25.39	25.39T	
Sales Tax		7.40%	1.88	

11.21.14  
Cannon #C16  
Allen County  
Section: 15  
Township: 26  
Range: 18

# 71730

POSTED

11-20-14

PAID

3712

12-5-14

Hooked onto 2 7/8" casing. Established circulation with 4 barrels of water, 2 GEL, METSO, COTTONSEED ahead, blended 95 sacks of 2% cement, dropped rubber plug, and pumped 4.7 barrels of water

<b>Total</b>	\$2,708.52
<b>Payments/Credits</b>	\$0.00
<b>Balance Due</b>	\$2,708.52