

Supply Well Service, LLC

9245 Ford Road
Chanute, KS 66720

Date	Invoice #
11/18/2014	50153

Cement Treatment Report

Multi Plex Resources, LLC
1300 Rolling Brook Drive, Ste. 605
Baytown, TX 77521

(x) Landed Plug on Bottom at 800 PSI
 () Shut in Pressure psi
 (x) Good Cement Returns
 () Topped off well with _____ sacks
 (x) Set float shoe

TYPE OF TREATMENT: Production Casing
 HOLE SIZE: 5 7/8"
 TOTAL DEPTH: 825

Well Name	Terms	Due Date	
	Net 15 days	12/18/2014	
Service or Product	Qty	Per Foot Pricing/Unit Pricing	Amount
Run and cement 2 7/8" (Casing Depth 820)	825	3.25	2,681.25
Rubber Plug	1	25.39	25.39T
Sales Tax		7.40%	1.88

8
11.18.14
Cannon #CI-2
Allen County
Section: 15
Township: 26
Range: 18

71330

PAID
3704
11-21-14

POSTED
11-20-14

Hooked onto 2 7/8" casing. Established circulation with 3.5 barrels of water, 2 GEL, METSO, COTTONSEED ahead, blended 108 sacks of 2% cement, dropped rubber plug, and pumped 4.7 barrels of water

Total	\$2,708.52
Payments/Credits	\$0.00
Balance Due	\$2,708.52