

Play Well Service, LLC

9245 Ford Road
Chanute, KS 66720

| Date | Invoice # |
|------------|-----------|
| 11/10/2014 | 50129 |

Cement Treatment Report

Multi Plex Resources, LLC
1300 Rolling Brook Drive, Ste. 605
Baytown, TX 77521

(x) Landed Plug on Bottom at 600 PSI
 () Shut in Pressure psi
 (x) Good Cement Returns
 () Topped off well with _____ sacks
 (x) Set float shoe

TYPE OF TREATMENT: Production Casing
 HOLE SIZE: 5 7/8"
 TOTAL DEPTH: 845

| Well Name | Terms | Due Date | | |
|--|-------------|-------------------------------|----------|--|
| | Net 15 days | 12/10/2014 | | |
| Service or Product | Qty | Per Foot Pricing/Unit Pricing | Amount | |
| Run and cement 2 7/8" (Casing Depth 835) | 845 | 3.25 | 2,746.25 | |
| Rubber Plug | 1 | 25.39 | 25.39T | |
| Sales Tax | | 7.40% | 1.88 | |

11.7.14
 Cannon #CI-5 ✓
 Allen County
 Section: 15
 Township: 26
 Range: 18

71730

POSTED
11/2014

PAID
3698
11-17-14

Hooked onto 2 7/8" casing. Established circulation with 1.5 barrels of water, GEL, METSO, COTTONSEED ahead, blended 112 sacks of 2% cement, dropped rubber plug, and pumped 4.8 barrels of water

| | |
|-------------------------|------------|
| Total | \$2,773.52 |
| Payments/Credits | \$0.00 |
| Balance Due | \$2,773.52 |