

Play Well Service, LLC
 245 Ford Road
 Chanute, KS 66720

Date	Invoice #
11/10/2014	50130

Cement Treatment Report

Multi Plex Resources, LLC
 1300 Rolling Brook Drive, Ste. 605
 Baytown, TX 77521

- (x) Landed Plug on Bottom at 850 PSI
- () Shut in Pressure psi
- (x) Good Cement Returns
- () Topped off well with _____ sacks
- (x) Set float shoe

TYPE OF TREATMENT: Production Casing
 HOLE SIZE: 5 7/8"
 TOTAL DEPTH: 835

Well Name	Terms	Due Date	
	Net 15 days	12/10/2014	
Service or Product	Qty	Per Foot Pricing/Unit Pricing	Amount
Run and cement 2 7/8" (Casing Depth 826)	835	3.25	2,713.75
Rubber Plug	1	25.39	25.39T
Sales Tax		7.40%	1.88
<div>11.5.14 Cannon #CI-7 ✓ Allen County Section: 15 Township: 26 Range: 18</div> <div># 71730 POSTED 11-20-14</div> <div>PAID 3698 11-17-14</div>			

Hooked onto 2 7/8" casing. Established circulation with 2 barrels of water, GEL, METSO, COTTONSEED ahead, blended 101 sacks of 2% cement, dropped rubber plug, and pumped 4.8 barrels of water

Total	\$2,741.02
Payments/Credits	\$0.00
Balance Due	\$2,741.02