## Kepley Well Service, LLC

19245 Ford Road Chanute, KS 66720

Date	Invoice #		
1/3/2015	50230		

**Cement Treatment Report** 

Multi Plex Resources, LLC 1300 Rolling Brook Drive, Ste. 605 Baytown, TX 77521 (x) Landed Plug on Bottom at 800 PSI
() Shut in Pressure psi
(x)Good Cement Returns
() Topped off well with\_\_\_\_\_\_ sacks
(x) Set float shoe

TYPE OF TREATMENT: Production Casing HOLE SIZE: 5 5/8"
TOTAL DEPTH: 860

Well Name	Terms	Due Date			
	Net 15 days	2/2/2015			
Service or Product		Qty	Per Foot Pricing/Unit Pricing		Amount
Run and cement 2 7/8", casing depth 835		860		3.25	2,795.00
Plug Sales Tax		1		25.39 7.40%	25.39T 1.88
12.13.14 Cannon #C17 Allen County Section: 15 Township: 26 Range: 18				11/30 25/ED 1-2015 23/37/D 1-15-15	
				Total	\$2,822.27

Hooked onto 2 7/8" casing. Established circulation with 3.5 barrels of water, 2 GEL, METSO, COTTONSEED ahead, blended 87 sacks of 2% cement, dropped rubber plug, and pumped 4.8 barrels of water

Total	\$2,822.27
Payments/Credits	\$0.00
Balance Due	\$2,822.27