

# Kepley Well Service, LLC

19245 Ford Road  
Chanute, KS 66720

Date

Invoice #

1/13/2015

50245

## Cement Treatment Report

Multi Plex Resources, LLC  
1300 Rolling Brook Drive, Ste. 605  
Baytown, TX 77521

- (x) Landed Plug on Bottom at 800 PSI  
( ) Shut in Pressure psi  
(x) Good Cement Returns  
( ) Topped off well with \_\_\_\_\_ sacks  
(x) Set float shoe

TYPE OF TREATMENT: Production Casing  
HOLE SIZE: 5 5/8"  
TOTAL DEPTH: 835

Well Name	Terms	Due Date	
	Net 15 days	2/12/2015	
Service or Product	Qty	Per Foot Pricing/Unit Pricing	Amount
Run and cement 2 7/8 (Casing Depth 830)	835	3.00	2,505.00
Rubber Plug	1	25.39	25.39T
Sales Tax		7.40%	1.88
<div>1-9-15 Cannon #C18 Allen County Section: 15 Township: 26 Range: 18</div> <div>#71730 POSTED 1-20-15 PAID 3241 1-30-15</div>			

Hooked onto 2 7/8" casing. Established circulation with 3.8 barrels of water, 2 GEL, METSO, COTTONSEED ahead, blended 87 sacks of 2% cement, dropped rubber plug, and pumped 4.8 barrels of water

Total	\$2,532.27
Payments/Credits	\$0.00
Balance Due	\$2,532.27