

Kepley Well Service, LLC

19245 Ford Road
Chanute, KS 66720

Date	Invoice #
12/2/2014	50180

Cement Treatment Report

Multi Plex Resources, LLC
1300 Rolling Brook Drive, Ste. 605
Baytown, TX 77521

(x) Landed Plug on Bottom at 800 PSI
 () Shut in Pressure psi
 (x) Good Cement Returns
 () Topped off well with _____ sacks
 (x) Set float shoe

TYPE OF TREATMENT: Production Casing
 HOLE SIZE: 5 7/8"
 TOTAL DEPTH: 847

Well Name	Terms	Due Date
	Net 15 days	1/1/2015

Service or Product	Qty	Per Foot Pricing/Unit Pricing	Amount
Run and cement 2 7/8" (Casing Depth 834)	847	3.25	2,752.75
Rubber Plug	1	25.39	25.39T
Sales Tax		7.40%	1.88

11.26.14
Cannon #C11
Allen County
Section: 15
Township: 26
Range: 18

71730

POSTED
12-20-14

PAID
3720
12-17-14

Hooked onto 2 7/8" casing. Established circulation with 1.5 barrels of water, 2 GEL, METSO, COTTONSEED ahead, blended 98 sacks of 2% cement, dropped rubber plug, and pumped 4.8 barrels of water

Total	\$2,780.02
Payments/Credits	\$0.00
Balance Due	\$2,780.02