# JAMES C. MUSGROVE

Petroleum Geologist, LLC 212 Main Street P.O. Box 215 Claflin, KS 67525

Office (620) 588-4250

Res. Claflin (620) 587-3444

Mai Oil Operations Dechant Unit #1 NE-NW-SE-NE (1430' FNL & 815' FEL) Section 17-20s-22w Ness County, Kansas

Page 1

# 5 1/2" Disposal Casing Set

Contractor:

Southwind Drilling Co. (rig #2)

Commenced:

January 19, 2015

Completed:

January 27, 2015

Elevation:

2200' K.B., 2198' D.F., 2191' G.L.

Casing program:

Surface; 8 5/8" @ 263'

Production, 5 1/2" @ 4613'

Sample:

Samples saved and examined 3600' to the Rotary Total Depth.

**Drilling time:** 

One (1) foot drilling time recorded and kept 3600' to the Rotary Total Depth.

Measurements:

All depths measured from the Kelly Bushing.

Drill Stem Tests:

There were one (1) Drill Stem Tests ran by Trilobite Testing Co.

Electric Log:

By Nabors, Dual Induction, Compensated Density/Neutron Log and Micro

Log.

<u>Formation</u>	Log Depth	Sub-Sea Datum		
Anhydrite	1428	+772		
Base Anhydrite	1464	+736		
Heebner	3684	-1484		
Toronto	3698	-1498		
Lansing	3730	-1530		
Stark	3989	-1789		
Base Kansas City	4056	-1856		
Marmaton	4097	-1897		
Pawnee	4177	-1977		
Fort Scott	4260	-2060		
Cherokee Shale	4274	-2074		
Conglomerate	4330	-2130		
Mississippian "Osage"	4360	-2160		
Gilmore City	4481	-2281		
Viola	4551	-2351		
Simpson Shale	4723	-2523		
Arbuckle	4753	-2553		
Rotary Total Depth	4850	-2650		
Log Total Depth	4856	-2656		

Mai Oil Operations
Dechant Unit #1
NE-NW-SE-NE (1430' FNL & 815' FEL)
Section 17-20s-22w
Ness County, Kansas

Page 2

# SAMPLE ANALYSIS, SHOWS OF OIL, TESTING DATA, ETC.

# TOPEKA/TORONTO/LANSING SECTIONS

3600-4054'

There were several zones of well-developed porosity encountered in the drilling of the Topeka/Toronto/Lansing Sections but no shows of oil and/or gas was noted (see attached sample log/geologist report).

#### **MARMATON SECTION**

4097-4120' Limestone, white, cream, chalky, poor porosity, plus white chert, no shows.

4130-4150' Limestone, white, gray, oolitic, chalky, few with sparry calcite cement, no

shows.

4153-4175' Limestone, tan, gray, finely crystalline, slightly cherty, dense, no shows

plus maroon tinted limestone.

#### **PAWNEE SECTION**

4177-4200' Limestone, gray, finely crystalline, fair granular, slightly cherty (dense).

4200-4230' Limestone, as above.

4230-4256' Limestone, as above, dense; slightly argillaceous, no shows.

#### FORT SCOTT SECTION

4260-4273'

Limestone, gray, finely crystalline, few oolitic, dense, no shows.

# **CHEROKEE SECTION**

4278-4296' Limestone, white, gray, finely crystalline, chalky, no shows.

4300-4330' Limestone, gray, white, finely crystalline, chalky, few cherty, tan/gray

chert, no shows.

#### **CONGLOMERATE SECTION**

4331-4353' Chert, white, gray, yellow, boney, opaque, trace black stain, plus trace

white, very fine grained, calcareous, sand, poor porosity, plus black

stain, no shows.

#### **MISSISSIPPIAN SECTION**

# 'OSAGE"

4360-4365' Chert, white, cream, boney, fresh; trace brown spotty stain, trace of free

oil and no odor.

4365-4377' Chert, as above, few weathered brown stain, trace of free oil and no odor

in fresh samples.

Mai Oil Operations
Dechant Unit #1
NE-NW-SE-NE (1430' FNL & 815' FEL)
Section 17-20s-22w
Ness County, Kansas

Page 3

Drill Stem Test #1		4282-4371
	Log Measurements	(4288-4377)

Times:

30-30-30-45

Blow:

**Strong** 

Recovery:

1290' muddy water

Pressures:

ISIP 1360 psi FSIP 1375 psi IFP 82-374 psi FFP 381-625 psi

HSH 2126-2080

4371-4400'

Chert, as above, glauconitic, boney in part, no shows.

4400-4420'

Chert; as above, plus dolomitic white, sucrosic, glauconitic, scattered porosity, no shows.

psi

4420-4440'

Dolomite and chert, as above.

4440-4460'

Dolomite and chert, as above, no shows.

4460-4481'

Dolomite, as above.

#### **GILMORE CITY SECTION**

4481-4523' Limestone, white/tan, fine and medium crystalline, few dolomitic, no

shows.

4523-4530'

Limestone, white, gray, oolitic, chalky, no shows.

4530-4551'

Limestone, as above, no shows.

## **VIOLA SECTION**

4554-4580' Dolomite, gray, white, sucrosic, dense, poor porosity, no shows.

4580-4600'

Dolomite, white, pink, peach, finely crystalline, sucrosic, poor visible

porosity, no shows.

4600-4620'

Dolomite, white, gray, fine to medium crystalline, few with chalky luster,

no shows.

4620-4650'

Dolomite, as above, plus white, gray boney chert.

4650-4680'

Dolomite, as above, plus white, cream gray opaque chert.

4680-4723'

Dolomite and chert as above.

# SIMPSON SECTION

4724-4734'

Sand, gray, sub-angular, dolomitic in part poorly developed, plus gray shale inclusions, no shows.

Mai Oil Operations Dechant Unit #1 NE-NW-SE-NE (1430' FNL & 815' FEL) Section 17-20s-22w Ness County, Kansas

Page 4

# **ARBUCKLE SECTION**

4753-4760'	Dolomite, tan, pink, finely crystalline, few sucrosic, fair porosity, no shows.
4760-4780'	Dolomite, pink, gray, tan, fine and medium crystalline, fair inter- crystalline porosity, no shows.
4780-4800'	Dolomite, as above, plus white chert, no shows.
4800-4820'	Dolomite, as above, sandy in part, no shows.
4820-4850'	Dolomite, as above, fair porosity, no shows.

Rotary Total Depth Log Total Depth 4850

4856

#### Recommendations:

The 5 ½" disposal casing was set and cemented on Mai Oil Operation Inc., Dechant Unit #1.

Respectfully yours,

James C. Musgrove Petroleum Geologist



## DRILL STEM TEST REPORT

Mai Oil Operations, Inc.

17-20s-22w Ness,KS

8411 Preston Rd STE 800 Dallas TX 75225-5520

Dechant Unit #1 Job Ticket: 61977

DST#: 1

ATTN: Jim Musgrove

Test Start: 2015.01.26 @ 05:27:00

#### GENERAL INFORMATION:

Time Tool Opened: 07:13:30

Time Test Ended: 11:53:30

Formation:

Mississippian

Deviated:

No Whipstock:

ft (KB)

Test Type: Conventional Bottom Hole (Initial)

Tester:

Shane Konzem

Unit No:

KB to GR/CF:

56

2200.00 ft (KB)

Reference Bevations:

2191.00 ft (CF) 9.00 ft

Interval: Total Depth:

4208.00 ft (KB) To 4371.00 ft (KB) (TVD)

4371.00 ft (KB) (TVD)

7.88 inches Hole Condition: Poor

Inside

625.10 psig @ 4293.50 ft (KB)

2015.01.26

Capacity:

8000.00 psig

Start Date: Start Time:

Hole Diameter:

Serial #: 6806

Press@RunDepth:

2015.01.26 05:28:00

End Date: End Time:

11:53:30

Last Calib.: Time On Btm: 2015.01.26


2015.01.26 @ 07:09:30 Time On Btm: 2015.01.26 @ 07:09:30 Time Off Btm: 2015.01.26 @ 09:36:30

TEST COMMENT: IFP 30 Minutes. BOB in 4 minutes and 45 seconds.

ISI 30 Minutes. No blow back.

FFP 30 Minutes. BOB in 5 minutes and 30 seconds.

FSI 45 Minutes. No blow back.



P	RESSUR	RE SUMMARY
ALIEA	Tonn	Ammetation

Time	Pressure	Temp	Annotation
Min.)	(psig)	(deg F)	
0	2126.65	112.17	Initial Hydro-static
4	82.19	112.63	Open To Flow (1)
34	374.06	126.93	Shut-In(1)
64	1360.72	126.44	End Shut-In(1)
65	381.73	126.10	Open To Flow (2)
94	625.10	126.85	Shut-In(2)
139	1375.66	124.86	End Shut-In(2)
147	2088.14	122.39	Final Hydro-static
	1		

#### Recovery

Length (ft)	Description	Volume (bbl)
156.00	Muddy water 50% Mud, 50% water	2.19
126.00	Muddy water 40% mud, 60% water	1.77
252.00	Muddy water 20% mud, 80% water	3.53
315.00	Muddy water 10% mud, 90% water	4.42
126.00	Muddy water 5% mud, 95% water	1.77
315.00	100% water	4.42

Gas Rates

Choke (inches) Pressure (psig) Gas Rate (Mcf/d)

Trilobite Testing, Inc

Ref. No: 61977

Printed: 2015.01.26 @ 16:48:32

ARROTEST STATES

# CEMENTING, INC.

Federal Tax I.D.# 20-2886107

one 785-483-2025

Home Office P.O. Box 32 Russell, KS 67665 No. 0779

Sec.	Twp. Range		County	State	On Location	Finish
Date 1-19-15 17	20 22	111	955	KS		16.30pm
		Location	on Bazine	30 BARU 95	40R) JW ZR	15 winte
Lease Dechant Unit	Well No. /	100	Owner			
Contractor Southwind #2			To Quality O	well Cementing, Inc	cementing equipmen	at and furnish
Type Job Ser face	40%		cementer an	d helper to assist ow	ner or contractor to d	o work as listed.
Hole Size 12/14	T.D. 264	TO VALUE	Charge /	ai Oil		
Csg. 8 5/8	Depth 263		Street		J. A. S. S. J. J. J. S. S.	
Tbg. Size	Depth	1.00	City	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	State	Art in the
Tool	Depth	, 18 July 18	The above wa	s done to satisfaction a	nd supervision of owner	agent or contractor.
Cement Left in Gsg. 15	Shoe Joint		Cement Amo	unt Ordered   70	90/403/122	1.681
Meas Line	Displace /5 3/4	1BL.	Contract the	· Le sou a residencia		
EQUIPN	WENT		Common		Profession in	
Pumptrk & No. Cementer Do	acs		Poz.: Mix		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Bulktrk No. Driver Orlver	K		Gel.	2	1973 19 19 19 19	a the training
Bulktrk 15 No. Driver No.	A		Calcium:	7	A constitution of the constitution of the	
JOB SERVICES		1. 1. 11.	Hulls	1		Street, B.
Remarks:	of the second second	ni verile	Salt	And the state of the state of		Carlotte Control
Rat Hole	ar Joseph and Arman	10000	Flowseal		raki ya yezhanek	2000
Mouse Hole	educini i produce de	of awa	Kol-Seal	A STATE OF THE STATE OF	i and the second	
Centralizers	11.		Mud CLR 48			· printers
Baskets		6. 94.) sec	.CFL-117 or C	D110 CAF 38	The second secon	
D/V or Port Collar	and the same of th	, 7,0 kgd	Sand	and the second	Aller and Aller	
8 18 on bottom	Sectation Mi	X	Handling	159		
170511 1 Sylve	<i>(4)</i>	1	Mileage			
				FLOAT EQUIPM	ENT	\$ 10 m
Cement ()	restated.		Guide Shóe			
at only mathematical contracts			Centralizer	and the second	San Contract Contract	· · · · · · · · · · · · · · · · · · ·
		al appropries.	Baskets	8 3/8 Swa	·C	
			AFU Inserts			9 - 14 A - 1
			Float Shoe	ALATA		
The Company of the Call And Call and			Latch Down			
	His town to make the	· vol. a.yb	The Water			
	All the state of t					
			Pumptrk Cha	rge -		
	· · · · · · · · · · · · · · · · · · ·	The state of	Mileage 2	JUV/ac	State of	F1 414
The state of the s	Commence of the second	the state of	- Lugar		Tax	
Land .	11/1/1	1.1997	Age of the	M	Discount	
Signature 4/11/16		71.70	Market in the		Total Charge	

# QUALITY OILWELL CEMENTING, INC. Federal Tax I.D.# 20-2886107

Phone 785-483-2025 Cell 785-324-1041

Home Office P.O. Box 32 Russell, KS 67665

No. 1125

Cell 785-324-1041	rion, su	A STATE OF THE STA	Capped Cappe		SLO perlau	Outuber of test of the		248431
	Sec.	Twp.	Range	(	County	State	On Location	Finish
Date /- 28-15	17	20	22	NE	55	KS		1,00pm
AN TOWN COLORS		Hermi	imasi si	Location	on Bazine	3wto ABRE	9= to UPORE	14 Yeswint
Lease Dechant	uni	+ [	Well No. /		Owner			The second of th
Contractor South wi	nd.	2			To Quality Oi	lwell Cementing, Inc	cementing equipmen	t and furnish
Type Job Production	1	obal cale			cementer and	d helper to assist ow	ner or contractor to d	o work as listed.
Hole Size 7/8	i same	T.D. 4	1850	1	Charge N	Tai oil	Operations	
Csg. 5 1/2	10000	Depth 46/3			Street	Em 1 Adr melmon	and the court and the	The later was the
Tbg. Size		Depth	Barrier Barre		City		State	
Tool	. 7 . 75	Depth			The above wa	s done to satisfaction a	nd supervision of owner	agent or contractor.
Cement Left in Csg. 20	5	Shoe J	oint 20.5		Cement Amo	ount Ordered /60	DSX 6/40 10	76 Salt
Meas Line		Displac	e 112 bl	15	2% ge	1 1/4 flows	Pul 1000	galand clear
A Real Property County Spirit	EQUIPM	MENT			Common			3
Pumptrk / No. Ceme Helper			RICK		Poz. Mix	HHARTEN	KI all place both or be	han a second
Bulktrk 3 No. Driver			Dova		Gel.	terhien mihros core	H. SECRETO NOM	S. COLLEGE
Bulktrk Pu No. Driver			BITT		Calcium	dictions to the action as		
JOB SE	RVICES	& REMA	RKS		Hulls	THE METERS OF MAKE	oss comercial av	
Remarks:			ic son ibnie v	will!	Salt			
Rat Hole 3051					Flowseal	of with the contempts	eg fot en ingerag	hand the same of t
Mouse Hole 2051					Kol-Seal		and the second services	The same of the sa
Centralizers 1, 3, 5,	7,10	2,	72		Mud CLR 48	1,000 00	4/	90-390-54
Baskets 4.73	,		d deed worman		CFL-117 or (	CD110 CAF 38		The second second
D/V of Port Collar 14	41	top	of sant	-73	Sand	and the second	JAUS new rolls.	ic i to leave
Pipe on botter	Ho	oked	+0 5/12	4	Handling			The sent make
Broke Circulat.	ion f	sr 10,	Drop -	bull	Mileage	Sant Control		and of the surviving
Sait 10 min So	F bu	11/20	Drod. ser	L	2	FLOAT EQUIPM	IENT	
Packer shoe.	Por	-D1	abogain	nud	Guide Shoe			,
Clear. Pluy Ra	+ ho	lew	30.5x		Centralizer	6	arruses to seek	T. M. LE.
mouse hole 205	x Ho	ot to	5/2 Pun	nped	Baskets	2		
110 st 40 to	un dens 1	9/54	Un Hook	"	AFU Inserts		and the second	
wash Dwank d	lines	5- R	eleased a	Plua	Float Shoe	ZABBYA	74 - 1 -	
Horambacka Dis	1900	cu	1112 5/56	nite	Latch Down	12 Plug		
unded Plug. Re	lease	1 AD	by held.		Packer	Shoe Po	rt coller	
Lift PSi	60	2						tration massis
o to 10 from the to also					Pumptrk Cha	arge		
Lanced Plug	PS!	150	U		Mileage			
theker set at	10	09 PS	1				Tax	
no Dan		1	1		in the se		Discount	
X Signature / Kelleam	A	and	leis				Total Charge	



WELL/PROJECT NO.

INVOICE INSTRUCTIONS

WELL TYPE

SECONDARY REFERENCE/

PART NUMBER

TICKET TYPE | CONTRACTOR | SERVICE | SALES

SERVICE LOCATIONS

REFERRAL LOCATION

PRICE

REFERENCE

CHARGE	TO: MAI OILO	porations	
ADDRES	STE, ZIP CODE	1	
0.	LEASE	COUNTY/PARISH	STATE
SWD	Declar + 1) ++	Don	NC

JOB PURPOSE

Nes

RIG NAME/NO.

coment port colles

DESCRIPTION

Declant Unit

MILEAGE

Peup Charge

+lorale

SWD rement

) rayour

WELL CATEGORY

DF

ACCOUNTING

ACCT

LOC

	TIC	KET	28235						
	PAG	1	OF						
DATE OWNER 27 Feb 15									
ORDER NO.									
W	ELL LOCATION								
4	UNIT PRICE		AMOUNT						
	5	00	10000						
	1250	00	125000						
	15	175	2205 00						
	20								
	- OK	25	175						
	42	00	77 250						
	42.	25	7000						
	42 200	25	762 50						
	42 200 1	25° 00 00 50	7000						
	43. 200 / 250	1	7000						
	42. 200 1 750	1	70018						

LEGAL TERMS: Customer hereby acknowledges and agrees to the terms and conditions on the reverse side hereof which include, but are not limited to, PAYMENT, RELEASE, INDEMNITY, and LIMITED WARRANTY provisions.

MUST BE SIGNED BY CUSTOMER OR CUSTOMER'S AGENT PRIOR TO START OF WORK OR DELIVERY OF GOODS

DATE SIGNED TIME SIGNED A.M. P.M.

**REMIT PAYMENT TO:** 

Opening tool pental

SWIFT SERVICES, INC. P.O. BOX 466 NESS CITY, KS 67560 785-798-2300

and the second second												
SUR	VEY	AG	REE	UN- DECIDED	DIS- AGRE				1141		4463	00
OUR EQUIPMENT WITHOUT BREAK							PAGE TOTA	4L	7/90			
WE UNDERSTOOM	DAND							17.50				
MET YOUR NEED	S?											
OUR SERVICE WA	S											
PERFORMED WIT	HOUT DELAY?											
WE OPERATED TO AND PERFORMED CALCULATIONS SATISFACTORILY	JOB						TAX					
ARE YOU SATISFI		SERVICI	E?									
	☐ YES			NO								
□ cus	TOMER DID NO	T WISH		TOTAL								

News Lity

Deation

U/M

QTY.

SHIPPED DELIVERED TO

WELL PERMIT NO.

QTY.

CUSTOMER ACCEPTANCE OF MATERIALS AND SERVICES The customer hereby acknowledges receipt of the materials and services listed on this ticket.

DATE 7 Feb 15 PAGE NO

CUSTOMER	014 01	PENATIONS	WELL NO.	SW	0	LEASE	+ 0,	17 JOB TYPE Comment part coller TICKET NO. 28235
CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUM		PRESSUR	E (PSI)	DESCRIPTION OF OPERATION AND MATERIALS
	130		(0.10)				07101110	1755k Sm Dament of 4th Florele
								23×52 Port loller - 144'
	1700			-				on loc TRK 114
				`				
	1255			1	1	1000	1000	test to peops; - hold
						1 The second		
	1258	3:	2			350		ivi rate 32 bpm @ 350 psi
	1302	32				350		mix SMD coment @ 11,200g
				de	1	200		110
	1324	32	75			400	**************************************	- cement to surface
								- Lanker
			8					Displace w/8661 4,0 (1405 port
								3.6
								close porteoller
	1330					1000	1000	test to parisi - held
	1342							Run 5 pixts
								9 /
	1353		25					Reverse hole claim
								- 2 count places -
								Pull tac
								urgh trick
								Rtck up
	1430							job complete
				1	1	13023	Tax sed	tech
					-	14500	The state of the s	E// U
								Plint, Pleine & 1310c
					1			
					-			