

Saman Sharifaie

Petroleum Geologist

GEOLOGISTS'S REPORT

DRILLING TIME AND SAMPLE LOG

COMPANY: **Martin Drilling Co., Inc.**
LEASE: **Katreek #1-8**

FIELD: **Wildcat**
LOCATION: **660' ENL & 1320' F.W.L.**
SEC: **8** TWP: **2S** RGE: **36W**
COUNTY: **Randolph** STATE: **Kansas**

CONTRACTOR: **Martin Drilling #8**
RTPD: **07/11/15** COMP: **072/1/15**
MUD UP: **3.21"** TYPE MUD: **Chemical**

SAMPLES SAVED FROM: **4000'** TO RTD
DRILLING TIME KEPT FROM: **4000'** TO RTD
SAMPLES EXAMINED FROM: **4000'** TO RTD

GEOLOGICAL SUPERVISION FROM: **3700'**
REFERENCE WELL: **MD/CJ-Katreek #1-SWD**

CONDUCTOR: **8-5/8" at 336'**
SURFACE: **8-5/8" at 336'**
PRODUCTION: **N/A**

CASING
ELECTRICAL SURVEYS
CND, DJL, MEL, SANC


FORMATION REFERENCE WELL: **MD/CJ-Katreek #1-SWD**

Formation	Sample Tops	E-log Tops	Strat Pos.
Anhydrite	3262 (+88)	3298 (+88)	+6
Base Anhydrite	3295 (+51)	3298 (+82)	+6
Trilobite	4087 (-227)	4091 (-231)	+5
Oolite	4222 (-863)	4221 (-861)	+6
Landing	4308 (-948)	4307 (-947)	+7
Prwnc	4570 (-1210)	4575 (-1215)	+7
BK/C	4704 (-1344)	4700 (-1340)	+2
Cherokee	4774 (-1414)	4776 (-1416)	+9
Mississippian	5002 (-1642)	5004 (-1644)	+8

REMARKS: Due to poor to fair shows of oil in multiple potential pay zones and negative DST results, it is recommended and agreed upon by all parties that this well be plugged and abandoned.

Respectfully Submitted,
Saman Sharifaie
Petroleum Geologist

API #15-153-21123
*Tops have been adjusted to electric logs



Deviation Survey @ 4526: 1/2

Morgan Mud @ 4598'
WT: 9.1
Vis: 60
WI: 6.8
CHI: 1,100
LCM: 8#

DST #5 (LKC H-J) 4438'-4526'

30-60-60-90
IF: Blow built to 4"
IS: No return
FF: Blow built to 5"
FSI: No return
Rec: 3' SOCM (98%M, 2%O), 63' SOWCM (92%M, 4%G, 2%O, 2%W), 186' MW w/trc O (56%M, 41%W, 3%G)

IFP: 17- 76
FFP: 3-29 - 521
ISIP: 1312
FSIP: 2297
FHP: 2225
BHT: 143°

Morgan Mud @ 4912'
WT: 9.3
Vis: 58
WI: 7.6
CHI: 1,000
LCM: 6#

Deviation Survey @ 5060: 1/2